NOTICE

All drawings located at the end of the document



ROCKY FLATS ENVIRONMENTAL	Manual No	21100-WP OU 01 5
TECHNOLOGY SITE	Procedure No	Table of Contents Rev 3
	Page	1 of 1
WORK PLAN FOR THE START UP	Effective Date	10/07/94
AND O&M OF THE IM/IRA	Organization	Environmental Management
FOR THE 881 HILLSIDE OU 1	•	

TABLE OF CONTENTS

WORK PLAN FOR THE STARTUP OPERATION AND MAINTENANCE OF THE IM/IRA FOR THE 881 HILLSIDE OPERABLE UNIT NO 1

Procedure <u>No</u>	<u>Title</u>	Rev <u>No</u>	Effective <u>Date</u>
	Detailed Table of Contents	0	03/03/92
ES	Executive Summary	0	03/03/92
1 0	Introduction	0	03/03/92
2 0	Background	0	03/03/92
3 0	Task Description	0	03/03/92
4 0	Project Management	0	03/03/92
5 0	Schedule	0	03/03/92
6 0	Quality Assurance Addendum	0	03/03/92
APPA	Appendix A Rocky Flats Plant Operable Unit 1 Grounds Treatment Facility Health and Safety Plan	water 1	10/07/94
APPB	Appendix B Respiratory Protection Plan	1	10/07/94
APPC	Appendix C Sampling and Analysis Plan	0	03/03/92
APPD	Appendix D Systems Operation Test Plan	0	03/03/92

ADM1 (RD

A-0001-0007 0

INFORMATION ONLY

ROCKY FLATS PLANT
OPERABLE UNIT 1
GROUNDWATER TREATMENT FACILITY
HEALTH AND SAFETY PLAN

HEALTH AND SAFETY PLAN

Rocky Flats Plant Operable Unit 1 Groundwater Treatment Facility Health and Safety Plan prepared by Resource Technologies Group, Inc

The site-specific health and safety plan has been written for the use of Resource Technologies Group, Inc., their employees, and subcontractors All EG&G personnel associated with this Project shall comply with all aspects of this plan as related to health, safety and emergency response

REVIEW AND APPROVAL

Liaison Officer

Environmental Restoration Health and

Safety Officer

ROCKY FLATS PLANT OPERABLE UNIT 1 GROUNDWATER TREATMENT FACILITY HEALTH AND SAFETY PLAN

Plan Approvals

Resource	Techno	iogies	Group.	inc

Bartley W Cours	7/30/93
Bartley W./Conroy //	Date '
Corporate Health and Safety Officer	

EG&G Rocky Flats

Mark Burnerte	8-6-93
Mark Burmeister	Date
Contractor's Technical Representative	

TABLE OF CONTENTS

10	INTR	ODUCTION AND PURPOSE PURPOSE	1 1 1 1
20	21	HISTORY, DESCRIPTION AND SCOPE OF WORK SITE HISTORY AND DESCRIPTION SCOPE OF WORK	2 1 2 1 2 3
30	3 1 3 2 3 3	TEM DESCRIPTION GROUNDWATER COLLECTION AND EQUALIZATION SYSTE ULTRAVIOLET (UV)/HYDROGEN PEROXIDE(H₂O₂) OX SYSTEM ION EXCHANGE SYSTEM ION EXCHANGE REGENERATION SYSTEM	3 1 M 3 1 (IDATION 3 1 3 3 3 3
40	PRO	JECT TEAM ORGANIZATION AND RESPONSIBILITIES	4 1
50	HEAL 5 1	5 1 1 Chemical Contaminant Hazards	5 1 5 1 5 1
	52	5 1 2 Process Chemical Hazard RADIOLOGICAL HAZARDS 5 2 1 External Radiation Exposure 5 2 2 Internal Radiation Exposure	5 12 5 14 5 15 5 16
	5 3 5 4	OPERATIONAL SAFETY HAZARDS ENVIRONMENTAL AND BIOLOGICAL HAZARDS	5 17 5 18
60	GENE 6 1	ERAL SITE REQUIREMENTS EMPLOYEE TRAINING 6 1 1 40 Hour Hazardous Waste Site Training 6 1 2 24 Hour On The Job Training 6 1 3 Respiratory Protection Training	6 1 6 1 6 2 6 2
	6 2 6 3 6 4 6 5	POSTING AND SITE ACCESS	6 3 6 5 6 5 6 5 6 8
70	EMEF 7 1 7 2	RGENCY RESPONSE PLAN FIRE HAZARDOUS SUBSTANCE RELEASE 7 2 1 Definitions	7 1 7 1 7 1 7 1

ı

7 2 2 Groundwater Treatment Facility Release Hazard Analys	
7 2 3 Initial Response Requirements 7 3 EMPLOYEE CONTAMINATION	76
7 3 EMPLOYEE CONTAMINATION 7 4 ACCIDENT/INJURY	7 7 7 7
7.5 COMMUNICATIONS	7 8
7 6 INCIDENT REPORTING	78
8 0 PERSONAL PROTECTIVE REQUIREMENTS	8 1
8 1 CLOTHING	8-4
8 2 RESPIRATORY PROTECTION	8 7
8 3 GENERAL REQUIREMENTS FOR PROCESS CHEMICAL HAI	NDLING8 9
8 4 GENERAL REQUIREMENTS FOR CHEMICAL STORAGE	8 10
8 5 CONFINED SPACE ENTRY	8 10
8 6 COMPRESSED GAS HANDLING AND STORAGE	8 10
9 0 AREA MONITORING	9 1
9 1 CHEMICAL MONITORING	9 1
9 2 RADIOLOGICAL MONITORING	93
9 2 1 Personnel and Equipment Contamination	9-4
9 2 2 Radioactive Air Particulate Monitoring	9-4
9 2 3 External Beta/Gamma Radiation Monitoring	9-4 9 5
9 2 4 Internal Radiation Exposure (Bioassay) Monitoring 9 3 MISCELLANEOUS MONITORING	95
9 3 1 Noise Monitoring	9-5
9 3 2 Heat Stress Monitoring	9-5
3 3 2 Treat Otress Monitoring	30
10 0 SITE CONTROL	10 1
APPENDIX A	
Material Safety Data Sheets	A 1
APPENIX B	
Standard Personal Protective Equipment	BI
v ·	
APPENDIX C	_
Respiratory Protection Aragram	C-

LIST OF FIGURES AND TABLES

FIGURES

Figure 2 1 881 Hillside Area Site Map	2 2
Figure 2 2 881 Hillside Area Site Map	2 5
Figure 3 1 Process Flow Diagram	3 2
Figure 4.1 Health and Safety Organization	4 2
Figure 6 1 Health and Safety Plan Acknowledgement Form	6-4
Figure 6 2 Safety Briefing Report	6 6
<u>TABLES</u>	
Table 4.1 Project Personnel	4 3
Table 4.2 Personnel Responsibilities	4-4
Table 5 1 Basis for Design of Groundwater IM/IRA Treatment System	5 2
Table 5.2 Summary of Organic and Inorganic Contaminants Detected in OU1 Influent	5-4
Table 5.3 Chemical Hazards Posed by Site Contaminants and Rou Exposure	ite of 5 5
Table 5.4 Chemical Hazards Posed by Process Chemicals and Routes of Exposure	5 12
Table 5.5 Radiological Contaminant Design Basis for IM/IRA Treatment System	5 14
Table 7 1 Spill Response Hazard Analysis	7-4
Table 8 1 Personal Protective Equipment Summary	8 2
Table 9 1 Monitoring Program Summary	9 2

10 INTRODUCTION AND PURPOSE

11 PURPOSE

This plan establishes requirements and provides guidelines for worker safety and hazard identification during subcontractor operation of the Groundwater Collection and Treatment System for Operable Unit No 1 (OU1) located at the Rocky Flats Plant in Golden Colorado. The purpose of this plan is to identify procedures for avoiding potential hazards from chemicals equipment or the environment and for responding to serious injury or accident. Revisions to this Plan will be made in accordance with the subcontractor Health and Safety Program and will be approved by EG&G.

20 SITE HISTORY, DESCRIPTION AND SCOPE OF WORK

2 1 SITE HISTORY AND DESCRIPTION

Operable Unit 1 is comprised of twelve sites in the 881 Hillside Area located at the southeast corner of the Rocky Flats Plant as shown in Figure 2.1. A brief description of each site in the 881 Hillside Area is presented below

Oil Sludge Pit (#102) A small pond located south of Building 881 was used for disposal of oil sludges in the late 1950 s


Chemical Burial Site (#103) A small pit was used for disposal of liquid wastes southeast of Building 881 in the early 1960 s

Liquid Dumping (#104) An area east of Building 881 was reportedly used for disposal of unknown liquids prior to 1969. This was not substantiated by results of drilling the area in 1987. Therefore, this site may not exist and it's location is not shown in Figure 2.1.

No 6 Fuel Oil Tanks (#105 1 and #105 2) Two fuel oil tanks are located south of Building 881 They are out of service and filled with concrete

Outfall Site (#106) An overflow line from the sanitary sewer sump south of Building 881 emerges on the slope below the building

Hillside Oil Leak (#107) Oil was discovered flowing from the Building 881 footing drain in early 1973. The source of the oil was never positively identified but the oil was collected in a skimming pond and



transported off site. There is an ongoing discharge of water from the footing drain

Multiple Solvent Spills (#119 1 and #119 2) Two areas east of Building 881 were used for barrel storage between 1969 and 1972

Radioactive Site (#130) Soils contaminated with low levels of radionuclides were placed on the hillside east of Building 881 and covered with soil between 1969 and 1972

Sanitary Sewer Line Leak (#145) The sanitary sewer line leaked on the hillside southwest of Building 881 in early 1981

Drum Storage Area (#177) Satellite collection and 90 day accumulation of RCRA regulated wastes at Building 885

Groundwater in the Building 881 Hillside area is contaminated with volatile organic compounds metals and radionuclides. Chemical Hazard Sheets for the various contaminants present may be found in Section 5.0

2 2 SCOPE OF WORK

As part of the Interim Measures/Interim Remedial Action (IM/IRA) Plan for Operable Unit Number 1 a groundwater handling and treatment facility was designed and constructed. The facility consists of the following systems

Groundwater Recovery and Storage System Recovery well and collection well pumps groundwater on an as available basis to one of two 15 000 gallon groundwater equalization/storage tanks

Process System Collected waters flow through a UV/H₂O₂ oxidation process to remove volatile organic constituents. The process water then flows to an ion exchange surge tank similar in size to the influent equalization tanks. Water is then pumped through the ion exchange system for removal of radionuclides alkalinity metals and total dissolved solids.

The treatment plant may be operated up to 7 days per week depending upon the amount of water requiring treatment. The subcontractor is responsible for operation and maintenance of the groundwater treatment facility. Figure 2.2 shows the location of the groundwater collection and treatment facility. Section 3.0 provides a more detailed description of the treatment system.

30 SYSTEM DESCRIPTION

The groundwater collection and treatment system is illustrated in Figure 3.1 and consists of the following subsystems

Groundwater collection and equalization

Ultraviolet (UV)/Hydrogen Peroxide (H₂O₂) Oxidation

Ion Exchange

Ion Exchange Regeneration and Regenerant Neutralization

Each of these process subsystems are discussed in detail below

3 1 GROUNDWATER COLLECTION AND EQUALIZATION SYSTEM

The groundwater collection system serves to divert and transfer design flows from recovery well pump P 100 and collection well pumps P 101 and P 102 to groundwater equalization/storage tanks T 201 and T 202 located on the south side of the treatment facility (Building 891). The raw water is pumped from the collection points to the equalization tanks through double-contained piping buried to prevent freezing. The influent piping is equipped with leak detection equipment to monitor for leaks. The equalization tanks have a capacity of 15 000 gallons each. Groundwater influent levels in the tank are continuously monitored and displayed. At design flow (30 GPM) the tanks can provide nearly 17 hours of equalization time.

3 2 ULTRAVIOLET (UV)/HYDROGEN PEROXIDE(H₂O₂) OXIDATION SYSTEM

The UV/H_2O_2 oxidation process is the first step in removing groundwater contaminants. The purpose of this process is to oxidize the volatile organic constituents using 50 percent H_2O_2 a strong oxidizer and UV light. The UV light serves to catalyze the oxidation by

converting the peroxide to a hydroxyl radical thus making it a more effective oxidant. The UV/H₂O₂ unit consists of two stainless steel reactor vessels each containing eight high intensity (high pressure) UV lamps. The lamps are installed inside quartz tubes to prevent direct contact of the water and the lamp. The reactors and control panel are mounted on a common skid.

Effluent from the UV/H₂O₂ process flows to the ion exchange surge tank (T 203) The purpose of the surge tank is to receive process water and store it until it is pumped to the ion exchange system

3 3 ION EXCHANGE SYSTEM

From the surge tank the water is pumped to two ion exchange columns (IX 1 and IX 2) in series. The first IX 1 contains a strong base anion resin in the chloride form for the removal of radionuclides. The second column IX 2 contains a weak acid cation resin in the hydrogen form for the removal of alkalinity and heavy metals. The groundwater flows from IX 2 to a degasifier where the liberated carbon dioxide escapes to the atmosphere. From the degasifier the water is pumped to the final two ion exchange columns (IX 3 and IX-4) in series for removing total dissolved solids (TDS). IX 3 contains a strong acid cation resin that removes remaining positively charged cations including excess hardness and metals. IX-4 with weak base anion resin is the last unit and removes excess negatively charged ions contributing to TDS. The treated groundwater then exits the building and flows to one of three 150 000 gallon final effluent storage tanks (T 205 T 206 and T 207) where it is held until analytical results indicate that it is acceptable for release to the south interceptor ditch

3 4 ION EXCHANGE REGENERATION SYSTEM

The ion exchange backwash and regeneration systems provide a means for maintaining the ion exchange resins while minimizing the volume of waste produced by the system

The caustic tank (T 208) contains sodium hydroxide and is used for regenerating IX-4 IX 1 is not regenerated but is monitored for removal efficiencies for radionuclides. The acid tank (T 209) contains hydrochloric acid and is used to regenerate IX-3 after which it is used to regenerate IX 2. Spent regenerant chemicals from both processes are neutralized in the neutralization tank (T 210) prior to removal by tank truck for final treatment. In addition to regeneration, the clean water storage tank (T 204) is used for storage of clean water for use in backflushing the ion exchange beds.

40 PROJECT TEAM ORGANIZATION AND RESPONSIBILITIES

EG&G Rocky Flats has overall responsibility for the Health and Safety Program at the Rocky Flats Plant. The subcontractor is specifically responsible for the Health and Safety Plan for the operation and maintenance of the groundwater treatment facility at OU1. The project Health and Safety Organization is shown in Figure 4.1. Table 4.1 presents lead management and field personnel on the project. Major responsibilities for key personnel are summarized in Table 4.2.

HEALTH AND SAFETY ORGANIZATION




TABLE 4 1
Project Personnel

COMPANY	<u>FUNCTION</u>	NAME	PHONE
EG&G	Contractor s Technical Representative	Mark Burmeister	966 5891
EG&G	ERM Health and Safety Officer	Keith Anderson	966 6979
RTG	Program Manager	Erich Tiepel	969 8511
RTG	Corporate Health and Safety Officer	Bartley Conroy	969 8511
RTG	Project Manager Health and Safety Specialist	Michael Griffin	969 8511
RTG	Project Health and Safety Officer Health and Safety Specialist	David Barnes	966-4310

TABLE 4 2
Personnel Responsibilities

Title	General Description		Responsibilities
Project Manager	Has authority to direct response operations Assumes total control over site activities Stop work authority	o	Prepares and organizes the background review of the situation Work Plan the Project Health and Safety Plan and the field team
		0	Ensures that the Work Plan is completed and on schedule
		O	Uses the Project Health and Safety Officer to ensure that safety and health requirements are met
		0	Prepares the final report and support files on the project activities
Project Health and Safety Officer	Advises the Project Manager on all aspects of health and safety on site Stops work if		o Periodically inspects protective clothing and equipment
	any operation threatens worker or public health or safety	0	Ensures that protective clothing and equipment are properly stored and maintained
		0	Implements the health and safety plan
		0	Conducts periodic inspections to determine if the Project Health and Safety Plan is being followed
		O	Knows emergency procedures evacuation routes and the telephone numbers for emergency response

Personnel Responsibilities

Title	General Description		Responsibilities
Project Health and S	Safety Officer (continued)	0	Sets up decontamination lines and the decontamination solutions appropriate for the type of chemical contamination on site
		0	Controls the decontamination of all equipment personnel and samples from the contaminated areas
		0	Assures proper disposal of contaminated clothing and materials
		0	Ensures that all required equipment is available
		o	Notifies EG&G emergency response personnel by telephone or radio in the event of a emergency
Subcontractor Health	n and Safety Officer	0	Develops corporate Health and Safety Guidelines
		0	Reviews Project Health & Safety Plans
		0	Develops site specific Health & Safety procedures with Project Health & Safety Officer
		o	Conducts inspections reviews compliance and review health & safety records

Personnel Responsibilities

Title	General Description		Responsibilities
Health and Safety Specialist	Provides support of operations involving monitoring of system processes and components for radiological contaminants		o Performs routine monitoring of lab and PPE waste materials in accordance with EG&G procedures to ensure control of radiological contaminants
			o Performs routine monitoring of sample shipment containers in accordance with EG&G procedures to ensure control of radiological contaminants
			o Performs special monitoring for radiological contaminants as required in accordance with EG&G procedures
Plant Operator	Provides daily operation and maintenance of plant Stop work authority	0	Follows standard operating procedures Verifies that plant is operating in a safe manner & complies with operations and environmental regulations
		0	Maintains daily records of all activities
		0	Conducts air monitoring as required
		0	Advises project health and safety officer of any unusual events

5 0 HEALTH AND SAFETY RISK ANALYSIS

The hazards associated with the operation of the groundwater treatment facility at OU1 include hazardous substances (chemical and radiological) physical hazards heat and cold hazards and possible construction hazards

5 1 HAZARDOUS SUBSTANCES

Potentially contaminated groundwater collected at the three collection points (P 100 P 101 and P 103) is expected to contain numerous hazardous substances. This Section identifies and addresses potential chemical hazards

5 1 1 Chemical Contaminant Hazards

Table 5 1 presents influent concentrations of site contaminants taken from the Design Basis of the 881 Hillside Area Groundwater IM/IRA Treatment System Table 5 2 presents a summary of actual sampling results for the period of April through September 1992 showing concentrations of contaminants listed in the Design Basis which were present and the number of times each contaminant was identified. It is apparent from a comparison of the data in Tables 5 1 and 5 2 that the Design Basis is a conservative estimate of potential contaminants in the OU1 influent stream. All contaminants in Table 5 2 are not present or are well below the Design Basis concentrations

Table 5 3 presents a summary of the chemical hazards routes of exposure and first aid for each contaminant listed in Tables 5 1 and 5 2

TABLE 5 1

Basis for Design of Groundwater IM/IRA Treatment System

Constituent	Unit	Influent Concentration*
<u>Organics</u>		
Methylene Chloride	<i>μ</i> g/l	<5 ^b
Acetone	μg/l	<10 ^b
Carbon Disulfide	<i>μ</i> g/l	<5 ^b
1 1 Dichloroethene	<i>μ</i> g/l	622
1 1 Dichloroethane	<i>μ</i> g/l	11
1 2 Dichloroethane	<i>μ</i> g/l	20
1 1 1 Trichloroethane	μg/l	945
Carbon Tetrachloride	μg/l	65
Trichloroethene	<i>μ</i> g/l	845
1 1 2 Trichloroethane	μg/l	<5 ^b
Tetrachloroethene	<i>μ</i> g/l	311
Toluene	<i>μ</i> g/l	<5 ^b
<u>Metals</u>		
Aluminum	mg/l	0 0703
Antimony	mg/l	0 0264
Arsenic	mg/l	0 0049
Barium	mg/l	0 1076
Beryllium	mg/l	0 0022
Cadmium	mg/l	0 0021
Cesium	mg/l	0 1515

TABLE 5 1 (Continued)

Basis for Design of Groundwater IM/IRA Treatment System

Constituent	Unit	Influent Concentration
Metals (Con't)		
Chromium	mg/l	0 0071
Copper	mg/i	0 0355
Iron	mg/l	0 0410
Lead	mg/l	0 0026
Lithium	mg/l	0 0450
Manganese	mg/l	0 0738
Mercury	mg/l	0 1290
Molybdenum	mg/l	0 0085
Nickel	mg/l	0 0683
Selenium	mg/l	0 1743
Silver	mg/l	0 0145
Strontium	mg/l	0 8287
Thallium	mg/l	0 0072
Vanadıum	mg/l	0 0391
Zinc	mg/l	0 1883

Based on a flow weighted average of the 881 Building footing drain (5 gpm) and alluvial groundwater at the 881 Hillside that would be collected in the french drain (2 gpm) Averages computed from the 1987 and 1988 data base except organics Organic concentrations determined from first and second quarter 1989 data

Detectable concentrations in some wells however blend should have non detectable concentrations

TABLE 5 2
Summary of Organic and Inorganic Contaminants Detected in OU1 Influent
April Through September, 1992

ANALYTE	NUMBER OF DETECTS	MEAN CONCENTRATION	STANDARD DEVIATION	NUMBER OF NONDETECTS				
Organιcs, μg/L								
Tetrachloroethene	13	18 84	8 41	0				
Acetone	1	27 0	0	12				
1 1 Dichloroethene	1	17 0	0	12				
1 1 1 Trichloroethane	1	18 0	0	12				
Trichloroethene	7	39 66	75 06	6				
Toluene	1	20 0	0	12				
	in	organics mg/L						
Aluminum	4	0 18	0 19	3				
Arsenic	4	0 003	0 0005	3				
Barıum	7	0 25	0 27	0				
Chromium	3	0 03	0 03	4				
Copper	5	0 01	0 01	2				
Iron	7	0 21	0 26	0				
Lead	2	0 01	0 0003	5				
Lithium	6	0 01	0 01	0				
Manganese	3	0 01	0 01	4				
Molybdenum	2	0 04	0 05	5				
Selenium	7	0 04	0 08	0				
Vanadium	2	0 02	0 02	5				
Zinc	7	0 047	0 01	0				

Note U = Below detection limits

TABLE 53

Chemical Hazards Posed by Site Contaminants and Route of Exposure

Contaminant (Synonyms) (Abbreviation	Concentrati	PEL (OSHA or TLV on (ACGIH) or REL	•	Physical/ Chemical Characteristic	Routes of	First Ald	Exposure Symptoms	IP eV
Methylene Chloride (Dichloro methane Methylene Dichloride)	<5	500 ppm	Carcinogen (5 000 ppm)	Colorless liquid with chloroform like odor BP 104 F UEL 22 / LEL 14 /	Inhalation Ingestion Contact	Artificial respiration Seek medical attention Imgate and wash affected area immediately	Fatigue weakness sleepiness lightheaded ness numb ness and tingling in limbs nausea eye and skin irritation	11 32
Acetone	<10	750 ppm	20 000 ppm	Colorless liquid with a fragrant mint like odor FI pt 1.4 F LEL 2.6 % UEL 12.8 % VP 266 mm Hg (@ 77 F)	Inhalation Ingestion Contact	Artificial respiration Seek medical attention Irrigate and wash affected area immediately	Eye nose and throat irritation headache dizziness dermatitis	9 69
on difide (Carbon Bisulfide)	<5	4 ppm	500 ppm	Colorless to faint yellow liquid UEL 50% LEL 13%	Inhalation Ingestion Absorption Contact	Artificial respiration Seek medical attention Irrigate and wash affected area immediately	Dizziness headache fatigue poor sleep nervousness psychosis coronary heart disease gastritis eye skin burns	10 08
1 1 Dichloro ethylene (Vinylidene chloride) (1 1 Dichlor oethene) (1 1 DCE)	622	1 ppm	Carcinogen	Colorless Liquid mild sweet odor LEL 73/ UEL 16%	inhalation Ingestion Contact	Artificial respiration Seek medical attention Irrigate and wash affected area immediately	Liver and kidney changes	9 65
1 1 Dichloro ethane	11	100 ppm	4 000 ppm	Colorless oily liquid Chloroform like odor	Inhalation Ingestion Contact	Artificial respiration Seek medical attention Imgate and wash affected area immediately	CNS depression liver and kidney damage skin irritation	11 06

Chemical Hazards Posed by Site Contaminants and Route of Exposure

Contaminant (Synonyms) (Abbreviation	Concentrati	PEL (OSHA) or TLV on (ACGIH) or REL	IDLH	Physical/ Chemical Characteristic	Routes of	First Aid	Exposure Symptoms	IP eV
1 2 Dichloro ethene (1 2 Dichloro ethylene)	2	200 ppm	4 000 ppm	Coloriess liquid with slightly acrid chloroform like odor UEL 12 8% LEL 5 6 %	inhalation ingestion Contact	Artificial respiration Seek medical attention Irrigate and wash affected area immediately	Eye irritation CNS depression Respiratory system	9 65
1 1 1 Trichloro ethane (Methyl Chloroform) (1 1 1 TCA)	945	350 ppm	1 000 ppm	Colorless liquid mild sweet odor LEL 75% UEL 125%	inhalation Ingestion Contact	Artificial respiration Seek medical attention Irrigate and wash affected area immediately	Eye and skin irritation dermatitis headache drowsiness	11 00
Carbon Tetrachloride (Tetrachloro methane)	65	2 ppm	Carcinogen (300 ppm)	Colorless liquid sweet odor not combustible VP 91 mm	Inhalation Ingestion Absorption Contact	Artificial respiration Seek medical attention Irrigate and wash affected area immediately	CNS depression nausea and vomiting liver and kidney damage skin irritation	11 47
Trichloro ethylene (Ethylene Trichloride) (TCE) (Trichloro ethene)	845	50 ppm	Carcinogen (1 000 ppm)	Colorless liquid sweet odor LEL 8% UEL 10 5%	Inhalation Ingestion Contact	Artificial respiration Seek medical attention Irrigate and wash affected area immediately	Headache vertigo visual disturbance vomiting nausea eye and skin irritation	9 45
1 1 2 Tri chloroethane	<5	10 ppm	Carcinogen (500 ppm)	Chloroform like odor Non combustible	Inhalation Ingestion Absorption Contact	Artificial respiration Seek medical attention Irrigate and wash affected area immediately	Carcinogen Irritate eyes nose throat cramps vomiting diarrhea affects sleep and appetite	11 00
Tetrachloro ethylene (Perchloro ethylene) (Tetrachloro ethene) (Perchlor)	311	25 ppm	Carcinogen (500 ppm)	Colorless liquid with sweet odor Not combustible VP 14 mm Hg	inhalation ingestion Contact	Artificial respiration Seek medical attention Irrigate and wash affected area immediately	Eye Nose throat stritation nausea flush face vertigo headache liver kidney CNS	9 32

Chemical Hazards Posed by Site Contaminants and Route of Exposure

Contaminant (Synonyms) (Abbreviation	Design Basis Concentrations) <i>µ</i> g/l	PEL (OSHA) or TLV on (ACGIH) or REL	IDLH	Physical/ Chemical Characteristic	Routes of	First Ald	Exposure Symptoms	IP eV
Toluene (Methyl Benzene) (Methyl Benzol)	<5	100 ppm	2 000 ppm	Colorless liquid with a sweet pungent odor UEL 71%	Inhalation Ingestion Absorption Contact	Artificial respiration Seek medical attention Irrigate and wash affected area immediately	Fatigue weakness confusion dizziness headache dilated pupils nervousness insomnia	8 82
Aluminum	0 0703 mg/l	15 mg/m (Total) 5 mg/m³ Respirable)	NA	Silvery ductile metal	Inhalation	NA	Pulmonary fibrosis possibly Alzheimer	N/A
Antimony	0 0264 mg/l	0 5 mg/m³	80 mg/m³	Silvery white metal	Inhalation Contact	Artificial respiration Seek medical attention Irrigate and wash affected area	Irritates eyes nose throat cramps vomiting diarrhea affects sleep and appetite	N/A
Arsenic	0 0049 mg/l	0 010 mg/m³	Carcinogen (100 mg/m)	Silver-gray or tın white brittle solid	Inhalation Absorption Contact Ingestion	Irrigate and wash affected area immediate medical attention	Nasal ulceration GI disturbances respiratory irritation	N/A
Barium	0 1076 mg/l	0 5 mg/m	1 100 mg/m	Silver-white slightly lustrous	Inhalation Ingestion Contact	Artificial respiration Seek medical attention Irrigate and wash affected area immediately	Irritates eyes nose throat upper respiratory GI muscle spasm slow pulse skin burns	N/A
Beryllium	0 002 2 mg/l	0 002 mg/m³	Carcinogen (10 mg/m³)	Metal a brittle grey white solid noncombus tible slight explosion hazard in dust or powder form	Inhalation	For eye exposure irrigate eyes immediately	Respiratory symptoms fatigue weakness weight loss	N/A

Chemical Hazards Posed by Site Contaminants and Route of Exposure

Design PEL (OSHA)

Contaminant Synonyms) Abbreviation	Concentra	or TLV ition (ACGIH) or REL	IDLH	Physical/ Chemical Characteristic		First Aid	Exposure Symptoms	IP eV
Cadmium	0 0021	0 2 mg/m	Carcinogen (50 mg/m)	Silver white blue tinged solid	Inhalation Ingestion	Artificial respiration Seek medical attention	Pulmonary edema cough tight chest chills muscle aches nausea vomiting diarrhea	N/A
Cesium	0 1515	NA	No Evidence	Silver white ductile metal or silvery liquid	Inhaiation Ingestion	Artificial respiration Seek medical attention	Hyperirit ability spasms	N/A
Chromium	0 0071	1 mg/m	No Evidence	Blue-white to steel-gray lustrous solid	inhalation Ingestion	Artificial respiration Seek medical attention Irrigate and wash affected area immediately	Corrosive to skin and mucous membranes carcinogen of the lungs nasal cavity stomach larynx	N/A
Copper	0 0355	1 mg/m³	No Evidence	Reddish lustrous malleable solid	Inhalation Ingestion Contact	Artificial respiration Seek medical attention Irrigate and wash affected area immediately	Irritation of eyes and mucous membranes pharynx poison by ingestion metal taste damage of nervous system kidneys and liver	N/A
Iron	0 0410	10 mg/m	No Evidence	Silvery white tenacious lustrous ductile metal	Inhalation Ingestion	Artificial respiration Seek medical attention	Poison by intraperitoneal route tissue and lung irritant and carcinogen	N/A
Lead	0 0026	0 050 mg/m³	700 mg/m	Bluish-gray soft metal	Inhalation Ingestion Contact	Artificial respiration Seek medical attention Irrigate and wash affected area immediately	Carcinogen of lungs and kidneys affects CNS GI tract blood	N/A

Chemical Hazards Posed by Site Contaminants and Route of Exposure

Contaminant (Synonyms) (Abbreviation	Concentrati	PEL (OSHA) or TLV on (ACGIH) or REL	idlh	Physical/ Chemical Characteristic	Routes of	First Ald	Exposure Symptoms	IP eV
Lithium	0 0450	NA .	NA	Silver colored light metal	inhalation ingestion	Artificial respiration Seek medical attention Irrigate and wash affected area immediately	Reacts with body moisture to cause burns toxic to CNS	N/A
Manganese	0 0738	5 mg/m	No Evidence	Silvery or reddish gray solid brittle combustible	Inhalation Ingestion	Artificial respiration seek medical attention	Parkinson s CNS and lung damage sleepiness vomit weakness tremors	N/A
Mercury	0 1290	0 01 mg/m³	10 mg/m	Silvery mobile odorless liquid	Inhalation Ingestion Contact Absorption	Artificial respiration Seek medical attention imgate and wash affected area immediately	Eye and skin imtant poison by inhalation cough tremor headache irritability GI and CNS affected	N/A
Molybdenum	0 0085	10 mg/m (Insoluble)	No Evidence	Dark gray or black powder with a metallic luster	inhalation ingestion	Artificial respiration Seek medical attention immediately	irritates eyes nose and throat diahrrea list lessness liver kidney damage	N/A
Nickel	0 0683	1 mg/m³ (Insoluble) 0 1 mg/m (Soluble)	Carcinogen (No Evidence)	Silvery white hard malleable and ductile metal	inhalation Ingestion Contact	Artificial respiration Seek medical attention Irrigate and wash affected area immediately	Nasal lung and skin irritant carcinogenic	N/A
Selenium	0 1743	0 2 mg/m	Unknown	Steel gray nonmetallic element combustible	Inhalation Absorption Ingestion Contact	Artificial respiration Seek medical attention Irrigate and wash affected area immediately	irritated eyes nose throat GI distress chills headache	N/A

TABLE 5 3 (Continued)

Chemical Hazards Posed by Site Contaminants and Route of Exposure

ACGIH American Conference of Governmental Industrial Hygienists

C Ceiling-Concentration shall not be exceeded at any time

CNS Central Nervous System

Fl pt Flash point-closed cup unless otherwise noted

IDLH Immediately Dangerous to Life and Health Maximum concentration from which one could escape within 30 minutes without

experiencing any irreversible health effects

IP Ionization potential (eV)
LEL Lower Explosive Limit
mg/m milligrams per cubic meter

N/A Not applicable
NA Not available

OSHA Occupational Safety and Health Administration

Permissible Exposure Limit-Concentration that nearly all workers may be repeatedly exposed day after day without adverse effect

(Based on an 8 hour workday and 40-hour workweek)

PPM Parts Per Million

TLV Threshold Limit Value-Concentration that nearly all workers may be repeatedly exposed day after day without adverse effect. (Based

on an 8 hour workday and 40-hour workweek)

UEL Upper Explosive Limit

 μ g/m micrograms per cubic meter

VP Vapor Pressure at 68 F in millimeters (mm) mercury (Hg) unless otherwise noted

References

PEL

Air Contaminants Permissible Exposure Limits (29 CFR 1910 1000)

American Conference of Governmental Industrial Hygienists Threshold Limit Values and Biological Exposure Indices for 1990 to 1991

National Institute of Occupational Safety and Health Pocket Guide to Chemical Hazards June 1990

N Irving Dangerous Properties of Industrial Materials Van Nostrand Reinhold Company New York 1979

TABLE 5 3 (Continued)

5 1 2 Process Chemical Hazards

In addition to the hazards posed by contaminants contained in the influent waste stream chemicals used in the treatment process pose a hazard to personnel. Table 5.4 presents a summary of the chemical hazards routes of exposure and first aid for each process chemical used in the groundwater treatment. Material Safety Data sheets are contained in Appendix A.

TABLE 5 4

Chemical Hazards Posed by Process Chemicals and Routes of Exposure

CHEMICAL EXPOSURE	CONCEN				YSICAL/ Mical	ROUTES OF	
(Synonyms)	TRATION	TLV/PEL	IDLH	CHARACTERIST	ICS EXPOSU	IRE FIRST AID	SYMPTOMS
Hydrochloric Acid	35 /	5 ppm (7 mg/m³)	100 ppm	Colorless liquid	Inhalation Ingestion Contact	Artificial respiration Seek medical attention Irrigate and wash affected area immediately	Nose and throat irritation burns throat and eyes cough choking
Sodium Hydroxide (Caustic Soda) (Lye)	50 % Solution	2 mg/m³	250 mg/m	White odorless solid before mixing disagreeable sweet odor in solution	Inhalation Ingestion Contact	Artificial respiration Seek medical attention Irrigate and wash affected area immediately	Severe skin irritation nose irritation temporary loss of hair
Liquid Nitrogen	100/	None	None	BP 3204F	Inhalation Contact	Artificial respiration Wash skin off with tepid water	Asphyxiant at high concentrations Freezes tissue narcotic at high concentrations and pressure
Hydrogen Peroxide	50 /	1 ppm	75 ppm	Colorless liquid with a slightly sharp odor Noncombustible	Inhalation Ingestion Contact	Artificial respiration Seek medical attention Imigate and wash affected area immediately	Eye nose and throat irritation corneal ulcer

Chemical Hazards Posed by Process Chemicals and Routes of Exposure

_				_	_	_
-	u۱	æ	IC	A		
_	77 1			-	ш.	

CHEMICAL EXPOSURE	CONCEN			CHE	MICAL	ROUTES OF	
(Synonyms)	TRATION	TLV/PEL	IDLH	CHARACTERIST	TCS EXPOSE	URE FIRST AID	SYMPTOMS
Nitrogen Compressed Gas	100 /	Simple Asphyxiant	Simple Asphyxiant	Coloriess odoriess gas	inhalation	Move to fresh air Artificial respiration if required	ACUTE Rapid respiration muscular incoordination fatigue nausea vomiting and loss of consciousness
Hydrogen Compressed Gas	100%	Simple Asphyxiant	Simple Asphyxiant	Odoriess coloriess tasteless gas	Inhalation	Move to fresh air: Artificial respiration if required	ACUTE Rapid respiration muscular incoordination fatigue nausea vomiting and loss of consciousness
Helium Compressed Gas	>99 /	Simple Asphyxiant	Simple Asphyxiant	Colorless odorless tasteless inert gas	Inhalation	Move to fresh air: Artificial respiration if required	ACUTE Rapid respiration muscular incoordination fattgue nausea vomiting and loss of consciousness
Compressed Air	100/	None	None	Coloriess gas	Inhalation	Inhalation at greater than atmospheric pressure without complete decompression may cause decompression sickness	Symptoms of decompression sickness include headache vertigo fatigue vorniting

5 2 RADIOLOGICAL HAZARDS

The radiological hazards associated with operation of the groundwater treatment facility arise from alpha beta and gamma radiations which are emitted from the present radionuclides during decay. Table 5.5 lists radionuclides and design basis concentrations. Alpha beta and gamma radiations are all forms of ionizing radiation. The chronic health hazards associated with exposure to ionizing radiation may include an increased risk of cancer and genetic effects. Various acute health effects are associated with high radiation exposures. An acute health effect is defined as an observable physiological change appearing within days to several weeks after exposure. However, radiation levels associated with operation of the groundwater treatment facility are well below those necessary to produce acute health effects. The actual radionuclide concentrations experienced in the plant influent water are well below these design basis values.

TABLE 5 5

RADIOLOGICAL CONTAMINANT DESIGN BASIS FOR IM/IRA TREATMENT SYSTEM

Constituent	Units	Influent Concentration ^a		
Total Radionuclides				
Gross Alpha	pCt/l	21 5		
Gross Beta	pCt/I	17 8		
Total Uranium	рСіЛ	15 4		
Strontium (89 90)	рСИ	<10		
Plutonium (239 240)	pCı/l	<0 01		
Americium (241)	pCi/l	<0 01		
Tritium	pCt/l	<400		

Based upon a flow weighted average of the 881 Building footing drain flow (5 gpm) and alluvial groundwater at the 881 Hillside that would be collected in the french drain (2 gpm). Averages computed from the 1987 and 1988 data base. Detectable concentrations in some wells. Blend should have no detectable concentration.

Groundwater treatment facility operators could be exposed to low levels of alpha beta and gamma radiation through exposure external beta/gamma radiation radioactive air particulates and radioactive contamination. The greatest potential for any health effects from radiation are at processes or material locations in which the contaminants contained in the water are concentrated (e.g. filters ion exchange resins). Monitoring methods worker exposure limits and administrative action levels for these radiation exposure aspects are separately addressed in this plan.

5 2 1 External Radiation Exposure

Both beta and gamma radiations are emitted by the radionuclides present in the groundwater treatment facility waste stream. External beta radiation cannot penetrate beyond the shallow layers of the skin or the lens of the eye and so associated hazards are confined to these areas. However, eye exposure to external beta radiation is greatly reduced or eliminated through the use of coveralls and eye protection.

External gamma radiation unlike beta radiation readily penetrates deep into the body and is therefore hazardous to internal organs. Clothing and eye protection are not effective at reducing external gamma radiation exposure. Three accepted methods to minimize gamma exposures are

the use of shielding between personnel and the radiation source minimizing time in the radiation area and maximizing distance from the radiation source

Due to low levels of gamma radiation external shielding designed to reduce gamma radiation exposure should not be necessary for workers at the groundwater treatment facility. Should external radiation be of concern the most effective methods of reducing worker exposure to external gamma radiation will be by posting areas where elevated

gamma exposure rates exist limiting the amount of time workers spend in these areas and maintaining a maximum distance from radiation sources

5 2 2 Internal Radiation Exposure

Alpha radiation is present in the groundwater treatment facility waste stream. Alpha radiation due to it's relatively large mass and charge does not pose an external hazard and will not penetrate the layer of dead skin cells. However, alpha radiation is a significant internal hazard due to the large amount of energy deposited in small, localized areas of internal organs. Alpha radiation is principally admitted to the body by inhalation of airborne contamination or ingestion, injection, or absorption of surface contamination.

Radioactive contamination existing in the form of loose material is capable of migrating or being transported by a variety of mechanisms such as movement of personnel vehicles equipment and wind. Several hazards are posed to workers concerning loose contamination. These hazards are inhalation ingestion injection and absorption of contamination.

Air particulates that are suspended or have settled out on horizontal surfaces (equipment) and have been resuspended pose an inhalation hazard. Drinking contaminated water eating contaminated food and/or transferring contamination to the mouth pose an ingestion hazard. Abrasions lacerations or punctures of the skin resulting from contact with contaminated surfaces pose an absorption hazard.

Exposure to radioactive contamination and the potential for internal contamination can be controlled by the proper use and removal of PPE administrative controls in controlled areas including prohibitions against smoking eating drinking and chewing and proper use of respirators when airborne contamination above prescribed limits is possible or suspected

5 3 OPERATIONAL SAFETY HAZARDS

The primary operational safety hazards and associated with this work and the control measures which will be implemented include the following

- <u>Injuries from moving and/or energized or pressurized parts and machinery</u> engineering controls include the installation of guards to prevent contact with moving machinery administrative controls include the use of lock out/tag out procedures to prevent injury from energized and/or pressurized systems
- Injuries from defective tools or mishandling of tools, materials, or equipment controls will include inspection of all tools prior to use for defects or damage and thorough training of operational personnel in the proper handling and use of the materials and equipment in use at the treatment facility—proper equipment use will be controlled through the use of approved Standard Operating Procedures
- Injuries from falls during work performed at above ground locations or from being struck by falling objects controls will include training and use of the proper fall protection equipment and use of hard hats where overhead hazards are present
- Injuries from slips, trips, and falls from working on wet surfaces or in inadequately illuminated work areas controls will include proper housekeeping and control of liquid and snow and ice on walking surfaces and the use of slip resistant surfaces adequate lighting will be provided and maintained in all work areas requiring access during darkness

- <u>Injury during work in confined spaces</u> All entries into designated confined spaces will be performed in accordance with current EG&G confined space policies and procedures by properly trained personnel
- Injuries from failure to wear proper personal protective equipment Section 8.0 of this Health and Safety Plan contains requirements for selection and use of personal protective equipment during all tasks associated with operation and maintenance of the treatment facility. Operational personnel receive training in the use of personal protective equipment and are required to read and acknowledge understanding of the contents of this plan. Additionally, Daily Safety Briefings are conducted at the beginning of each shift to discuss planned activities and control measures required. Including the proper personal protective clothing.

5 4 ENVIRONMENTAL AND BIOLOGICAL HAZARDS

In addition to the hazards described above during the operation and maintenance of the groundwater treatment facility there is the potential for worker exposure to high winds serious temperature extremes biological hazards. UV light and noise High winds pose a hazard to workers in areas outside the groundwater treatment facility building (Building #891). Outside work will be curtailed due to sustained winds following EG&G Plant announcements. Potentially serious temperature extremes could produce heat related illnesses such as heat stroke heat exhaustion and heat cramps for workers outside Building 891. During extreme cold weather the primary hazards of concern for workers outside will be hypothermia and frostbite.

The main biological hazards of concern primarily outside Building 891 will be insect and snake bites. Additionally equipment and machinery may generate levels of noise that could contribute to chronic hearing loss. UV light from the

 ${\rm UV/H_2O_2}$ system could cause UV radiation damage to the eyes and skin if the shields are removed from the viewing ports

60 GENERAL SITE REQUIREMENTS

Given the diverse nature and potential effects of the expected contaminants at the OU1 groundwater treatment facility careful safety precautions are necessary to ensure maximum protection of human health and the environment. This section presents general requirements which apply to all activities on the site. The purpose of these requirements is to ensure that operators and other subcontractor personnel involved with the operation of OU1 are properly prepared for the activities they will be performing

6.1 EMPLOYEE TRAINING

All operators and associated personnel working on this project shall be trained in accordance with the requirements of 29 CFR 1910 120. A training file for each subcontractor site employee will be maintained on site. This training file will include certificates and training records required by the subcontractor as well as site specific forms generated by EG&G. A training file containing the subcontractor records will also be maintained at the corporate office.

6 1 1 40 Hour Hazardous Waste Site Training

This training shall be a 40 hour hazardous waste course including the following elements

Hazard identification

Applicable regulations

Permissible exposure limits

Hazard communication (MSDS reference sources)

Physical & chemical effects of hazardous materials

Air monitoring and

Respiratory protection including fit testing

6 1 2 24 Hour On The-Job Training

In addition to 40 hour Hazardous Waste Site Training a site specific OSHA 24 hour on the job training shall be given to all workers and properly documented. This shall consist of a review of site contaminants and hazards, the contents of this plan, and the actions to be taken in the event of emergencies. Employees shall also be trained on the use of MSDS sheets which will be available to all personnel for chemicals used in the groundwater treatment facility.

6 1 3 Respiratory Protection Training

Respiratory Protection training is integral to the subcontractor Respiratory Protection Program. Field personnel will complete the level of respiratory protection training that is appropriate to their job description during initial 40 hour OSHA training and annually thereafter. Topics that will be covered for the subcontractor operations personnel at the groundwater treatment facility will include the following.

Overview of respiratory protection
Physiology of the respiratory system
Classification of respiratory hazards
Air purifying respirators
Respirator selection use and limitations
Fit testing maintenance and cleaning
Air supplying respirators/SCBAs/airline respirators
SCBA/airline respirators field exercise and
Examination

Page intentionally left blank

6 1 4 Supplemental Training

Supplemental training shall include the following

the EG&G Project Manager)

8 hour supervisor training (shift foremen Health and Safety Officer)

Current 8 hour refresher training (all employees)

Respiratory protection training (all employees) and

First aid and CPR training (at least one employee per shift)

Confined Space Entry Training (as determined by EG&G Project Manager)

Pressure Safety Awareness and Intermediate Pressure Safety (as determined by

The Project Manager shall be responsible for verifying the current status of training for all employees assigned to the project. Any deficiencies shall be cleared prior to the employee beginning work on the field portion of the project.

Finally all employees must read and acknowledge in writing that they have read this site specific Health and Safety Plan. A sample acknowledgement is shown on Figure 6.1 Blank acknowledgement forms must be kept in the operations office at OU1 at all times and original signed forms kept by the Project Manager in the project files. Subcontractor personnel shall also sign Health and Safety Plan Acknowledgements if they are working under the subcontractor Project Health and Safety Plan.

The preceding requirements are those that must be satisfied for any subcontractor field work regardless of the site. There are also several training requirements to satisfy the site specific requirements of both the subcontractor and EG&G. These site specific requirements include

EG&G Radiation Workers for Environmental Restoration Safety Training EG&G Waste Generator Non PA Training Course (for packaging waste)

FIGURE 6.1 HEALTH AND SAFETY PLAN ACKNOWLEDGEMENT FORM

RG	RESOURCE TECHNOLOGIES
DEU	GROUP INC

HEALTH AND SAFETY PROGRAM HEALTH AND SAFETY PLAN ACKNOWLEDGEMENT

Project Number	
Project Name Project Location	
-roject Location	
hereby acknowledge that I have been given a safety briefing on the work I am to do on the above-referenced site. I understand that the site may contain materials classified by EPA or others as potentially hazardous. I have read and understand the safety plans for this project and will adhere to the procedures contained therein. I have been instructed in and understand the use of the safety equipment for this project.	
Employee	
Date	
Print Name	
Signature	
Project Manager or Representative	
Date	
Print Name	
signature	

All operations personnel will receive site specific training pertaining to chemicals and materials used in the operation of the OU1 groundwater treatment facility regarding the routes of exposure and adverse health effects

6.2 MEDICAL MONITORING

In accordance with the 29 CFR 1910 all employees assigned to a field project at a hazardous waste site shall be part of a Medical Monitoring Program. The Project Manager shall be responsible for verifying the current medical monitoring status for all employees assigned to the project. Any deficiencies shall be cleared prior to the employee doing any field work on the field project. Medical qualification records will be submitted to EG&G for maintenance on site.

63 DAILY SAFETY BRIEFINGS

As described in Section 6.1 all workers shall receive a safety briefing on the contents of this plan prior to beginning work. In addition, a health and safety briefing shall be performed at the beginning of each shift. The briefing shall be conducted by the shift. Health and Safety Officer, and shall cover the specific tasks to be performed for that shift. Health and safety concerns for planned tasks shall be reviewed, and required procedures discussed. The attendees at the briefing, and the items discussed shall be documented in the daily Safety Briefing Report shown on Figure 6.2. A supply of blank Safety Briefing Forms will be kept in the operations office for OU1.

6 4 POSTING AND SITE ACCESS

The Rocky Flats Plant site is a controlled access area with the OU1 treatment facility located inside the perimeter Rocky Flats fencing. Access to the treatment facility is through the office at the facility and requires proper badging and clearance including a personal dosimeter. Access to the OU1 treatment facility shall be limited to

FIGURE 6 2 SAFETY BRIEFING REPORT

RESOURCE TECHNOLOGIES GROUP INC	SAFETY BRIEFING REPO	
Project Number	Name	
Project Location		
Project Manager		
	fficer	
Date	Weather	
Task Specific Safety Requ		
Task		
Personnel		
Name	<u>Assiar</u>	nment
Task Specific Safety Requi	urements	
Personnel <u>Name</u>	Assign	ment
Safety Requirements		

FIGURE 6 2 (CONTINUED)

RG	RESOURCE TECHNOLOGIES GROUP INC
	GROUP INC

HEALTH AND SAFETY PROGRAM SAFETY BRIEFING REPORT Page 2 of 2

Task Specific Safety Requirement	nts	
Task		
Personnel <u>Name</u>		Assignment
Safety Requirements	-	
Task Specific Safety Requirement		
Personnel Name		Assignment
Safety Requirements		
Briefing Acknowledgement	P inted Name	Signature
	. 11169 IVE	
Brieting Conque ed By		

The subcontractor operations and supervisory personnel in addition to appropriate EG&G personnel. Any maintenance or other personnel will be trained in accordance with the requirements presented in this section and also be accompanied by an operator

6 5 BUDDY SYSTEM

All work which requires an operator to directly handle sample or transport hazardous materials hazardous waste or waste containers at Rocky Flats requires the use of the buddy system. This includes process chemical preparation, drum or chemical transfers and maintenance. The buddy system ensures that each worker is observed by another worker who can provide rapid assistance in case of emergency. In addition, any work requiring greater than Level D protection requires use of the buddy system. Operators may monitor controls and gauges in the plant without use of the buddy system provided radio contact is maintained with the roving foreman. At no time shall any worker engage in any kind of emergency response without the use of the buddy system. Workers shall immediately evacuate the danger area upon discovery of a potential emergency situation.

70 EMERGENCY RESPONSE PLAN

This project involves the operation of an existing water treatment plant. Potential emergency situations during work at the OU1 Groundwater Treatment Facility include fire hazardous substance release employee contamination accidents and injuries. Safety precautions will be taken to avoid emergency situations. However, if an emergency does arise, the procedures described in this section will be followed. Also preparatory steps necessary for responding to an emergency situation are given below and they should be complied with before beginning any work at the site.

EG&G maintains an emergency response telephone extension of **2911** at Rocky Flats plant. Extension **2911** may be reached from any plant site telephone system instrument and will immediately connect the caller with the Fire Department, the Central Alarm Station, the Shift Superintendent and during first shift. Occupational Health

71 FIRE

All personnel should move or be moved to a safe distance from any area involved in a fire situation. The EG&G emergency extension at **2911** shall be called immediately. The Subcontractor Shift Foreman shall immediately notify the subcontractor and EG&G personnel as shown on page 7.8

7 2 HAZARDOUS SUBSTANCE RELEASE

7 2 1 Definitions

emergency response action is a response effort to an occurrence which results or is likely to result in an uncontrolled release of hazardous materials or substances. This does not include response to incidental releases of hazardous materials or substances.

dente and those

An **EMERGENCY RESPONSE** involves support efforts by employees from outside the immediate release area or by designated responders (e.g. HAZMAT Team or Radiological Assistance Team)

incidental Release includes spills leaks or other releases where the substance can be safely absorbed neutralized or otherwise controlled by employees or maintenance personnel in the immediate release area at the time of the release. It also includes releases of hazardous substances for which there is no potential safety or health hazard (i.e. fire explosion or chemical exposure) above the normal operating conditions in the work area. Use of additional personal protective equipment (e.g. chemical cartridge respirators) not used during normal work activities is not allowed.

RELEASE means any spilling leaking pumping pouring emitting emptying discharging or dumping of a hazardous material or hazardous waste <u>in any building/containment or to the environment</u>

REPORTABLE RELEASE are all solid and liquid releases of a hazardous material or a hazardous substance greater than or equal to one pound (or one pint for aqueous liquids) and all gaseous (gas/vapor) releases that threaten or occur inside or outside of any building/containment and that are unplanned

A list of hazardous and extremely hazardous substances (including radionuclides) is included as Attachment 1 to Section 4 0 of the Hazardous Waste Requirements Manual 1 10000 HWR

7 2 2 Groundwater Treatment Facility Release Hazard Analysis

Table 7.1 contains a hazard analysis of all materials at the Groundwater Treatment Facility that have the potential to be released and the appropriate level of personal protective equipment required for spill response

TABLE 7 1 SPILL RESPONSE HAZARD ANALYSIS

MATERIAL SPILLED	SPILL PROCEDURES	PERSONAL PROTECTIVE EQUIPMENT REQUIRED
Hydrochlonc Acid	Flush with water neutralize with soda ash or lime only with adequate ventilation as carbon dioxide is generated eliminate sources of ignition as hydrogen gas may be generated place in appropriate container for disposal	Level D Work clothes with plastic coated Tyvek safety shoes with neoprene boot covers safety glasses with full face shield elbow length neoprene or butyl gloves Level B No entry without SCBA in event of a spill of concentrated hydrochlonic acid
Sodium Hydroxide	Flush with water neutralize with dilute acid pick up spill with vacuum or pumping equipment place in appropriate container for disposal	Level D Work clothes with plastic coated Tyvek or apron elbow length neoprene gloves and overboots safety glasses will full face shield
Hydrogen Peroxide	Flush area with water place in appropriate container for disposal	Level D Work clothes with plastic-coated Tyvek safety shoes with neoprene boot covers safety glasses with full face mask neoprene or butyl gloves SA or SCBA ^b required if monitoring indicates levels above TWA of 1 ppm
Liquid Nitrogen	Shut off leak if it can be done without risk of skin contact and if ventilation is adequate. Evacuate area until ventilation can restore a safe oxygen level. Allow spilled liquid to evacuate.	Level D Work clothes with insulated gloves safety goggles. If spill is significant amount in a small area oxygen deficiency is a hazard and use of SCBA may be required.
Ion Exchange Resin	Sweep up Ion exchange resin on smooth surfaces may be slippery place in appropriate container for storage or disposal	Level D Work clothes safety glasses with side shields safety shoes

Notes

Supplied Air

Self Contained Breathing Apparatus

TABLE 7 1 (Continued) SPILL RESPONSE HAZARD ANALYSIS

MATERIAL SPILLED	SPILL PROCEDURES	PERSONAL PROTECTIVE EQUIPMENT REQUIRED
Nitrogen (Compressed Gas)	Evacuate and ventilate area Contact RFP HAZMAT (ext 2911) Ensure oxygen levels are above 19 5% Remove the leaking cylinder to a safe outdoors area if this can be done safely	Level D Work clothes with safety shoes and safety glasses Emergency response personnel to determine if oxygen deficiency is a hazard prior to entry
Hydrogen (Compressed Gas)	Shut off ignition sources due to fire and explosion hazard Contact RFP HAZMAT (ext 2911) Evacuate and ventilate area Ensure oxygen levels are above 195% Ensure combustible gas level are below 10% LEL Remove the cylinder to a safe outdoors area if this can be done safely	Level D Work clothes with safety shoes and safety glasses. Emergency response personnel to determine combustible gas levels and if oxygen deficiency is a hazard prior to entry
Helium (Compressed Gas)	Evacuate and ventilate area Contact RFP HAZMAT (ext 2911) Ensure oxygen levels are above 19 5% Remove the leaking cylinder to a safe outdoors area if this can be done safely	Level D Work clothes with safety shoes and safety glasses Emergency response personnel to determine if oxygen deficiency is a hazard prior to entry
Air (Compressed Gas)	Evacuate and ventilate area Remove the leaking cylinder to a safe outdoors area if this can be done safely	Level D Work clothes with safety shoes and safety glasses

7 2 3 Initial Response Requirements

If an employee properly trained in accordance with the requirement in Section 6.0 discovers an <u>incidental release</u> in his/her work area and is knowledgeable of the associated hazards the employee may take immediate action to contain and/or control the release (e.g. shut a valve to stop the flow). Such action shall not be undertaken without the presence of the shift foreman in accordance with Section 6.5. An <u>incidental release</u> may be cleaned up as part of the first response actions.

Note Action should only be taken if the employee can perform them in a safe manner, without endangering himself/herself or others

If the spill or release is life threatening or involves a fire the Shift Foreman shall immediately call the Plant Emergency Number (extension 2911). All other spills and releases shall be immediately reported to EG&G and the subcontractor supervision who will assess the event or condition to determine if an emergency response is required Supervision may request assistance as required of support groups (e.g. Industrial Hygiene Radiological Engineering etc.) to make this determination

If the event or condition requires an <u>emergency response</u> supervision shall immediately call the Plant Emergency Number (extension 2911 for life threatening emergencies) or the Shift Superintendent (extension 2914 for non-life threatening emergencies) for assistance. Containment measures shall only be performed by personnel with First Responder Operations Level training. Following containment of the spill adequately trained Groundwater Treatment Facility operations personnel or HAZMAT team members may perform cleanup operations.

7 3 EMPLOYEE CONTAMINATION

If any site worker experiences a failure or alteration of protective equipment that affects the protection factor that person and his/her coworker(s) will immediately leave the work area for which the PPE was required. Re entry to the secondary containment area will not be permitted until the equipment has been repaired or replaced. If any other incidents occur that involve the contamination or exposure of an employee to hazardous or toxic substances, the EG&G emergency extension at 2911 shall be notified immediately to dispatch the appropriate emergency personnel.

First aid or other decontamination procedures should be administered if they can be without endangering other operations personnel. A first aid kit will be located in the office area of the treatment facility. The Shift Foreman or operator shall notify EG&G and the subcontractor supervision immediately.

7 4 ACCIDENT/INJURY

In the event of an accident or other event that causes injury to operations or any other personnel present at the OU1 site the EG&G emergency extension at 2911 shall be notified immediately. The site Fire Department EMT's and Security will be dispatched immediately. Details of the emergency and the exact location must be given over the phone. Basic first aid may be administered by the subcontractor personnel until emergency medical assistance is available. Each shift will have a minimum of one subcontractor staff member trained in American Red Cross First Aid and CPR. A first aid kit will be kept in the office of the Groundwater Treatment Facility. Any non emergency medical situation such as minor cuts or sprains should be attended to at

EG&G Medical Building 122

The subcontractor Shift Foreman or operator shall immediately notify EG&G and the subcontractor supervision of any accident or injury

75 COMMUNICATIONS

The OU1 groundwater treatment facility consists of the treatment plant inside Building 891 and associated tankage outside the building in close proximity. The small work area and requirement of the buddy system during work activities allows face to face communication among workers. A phone is located in the office area of the treatment facility for communication in emergencies. Any work required at other areas of the EG&G plant site require the availability of two way radios for emergency use. The on site emergency phone number is 2911 which is the EG&G emergency extension.

76 INCIDENT REPORTING

The following list of supervisory personnel and their telephone numbers will be posted by the telephone(s) closest to ongoing field activities. One EG&G and subcontractor staff member will be notified using the call in order listed of any spill release personnel contamination accident or injury major equipment failure or out of specification discharge.

EMERGENCY TELEPHONE NUMBERS

EG&G OU1 Emergency Contacts			Telephone N	<u>umber</u>
Contact	Russ Cırıllo	ŧ	EG&G Phone Pager	966 5876 5477
Back-up	Mark Burmeister		EG&G Phone Pager	966 5891 4630
Back-up	Ty Vess		EG&G Phone Pager	966 6540 5476
Back-up	Marla Broussard		EG&G Phone Pager	966-8517 4010

If none of the EG&G personnel listed above are available, contact the EG&G Shift Superintendent at 966 2914

EG&G Emergency Response Extension 2911

RTG OU1 Emergency Contacts

RTG Project Manager Contact Mike Griffin	RTG Phone	969 8511
RTG Health and Safety Officer Contact Bart Conroy	RTG Phone	969 8511
RTG Program Manager Contact Erich Tiepel	RTG Phone	969 8511
RTG Site Health and Safety Officer Contact David Barnes	RTG Phone	966-4310

8 0 PERSONAL PROTECTIVE REQUIREMENTS

The purpose of personal protective equipment (PPE) including clothing is to shield or isolate individuals from the chemical physical and biological hazards that they may encounter at sites containing hazardous or toxic materials. The careful selection and use of PPE will protect the respiratory system, skin, eyes, face, hands, feet, head body, and hearing

No single combination of protective equipment and clothing is capable of protecting against all hazards and PPE must be used in conjunction with other protective methods. The use of PPE can in itself create significant worker hazards such as heat stress physical and psychological stress impaired vision mobility and communication.

Specific protective garments are selected on the basis of a variety of criteria. In general, the greater the level of PPE, the greater the associated risks. For any given situation, equipment, and clothing must be selected to provide an adequate level of protection. Over protection as well as under protection can be hazardous and should be avoided.

Table 8 1 summarizes PPE requirements for specific tasks associated with operation of the groundwater treatment facility. Non routine tasks which are not addressed in Table 8 1 will be addressed on a case by case basis by the subcontractor and the appropriate level of PPE will be determined with approval by EG&G. The following sections detail the criteria for selecting specific personal protective equipment (PPE) which will apply to this project.

TABLE 8 1
Personal Protective Equipment Summary

Task	Level	Body	Foot	Head ¹	Eye	Hand	Respirator ²
Operation of UV/H₂O	D	Work Clothes	Safety shoes	None Required	Safety Glasses	None Required	None required
Filling H O feed tank or working with H O feed system	D	Work Clothes	Safety shoes	None Required	Full face splash shield	Nitrile outer gloves with latex inner glove liners	None required
Changing UV buibs in UV/H O system	D	Work Clothes	Safety shoes	None Required	Safety Glasses	Leather work gloves	None required
Operation of IX	D	Work Clothes	Safety shoes	None Required	Safety Glasses with side shields	None required	None required
Operation of degasifier column	D	Work Clothes	Safety shoes	None Required	Safety Glasses with d shields	None required	None required
Operation of motorized pumps to transfer fluids	D	Work Clothes	Safety shoes	None Required	Safety glasses with side shields	Leather work gloves	None required
Removal and replacement of filter bags	D	Work Clothes	Safety shoes	None required	Safety glasses with side shields	Nıtrile gloves	None required
Cleaning UV lamps and changing bulbs	D	Work Clothes	Safety shoes	None Required	Safety glasses with side shields	Nitrile gloves	None required
Regeneration of IX columns	D	Work Clothes	Safety Shoes	None Required	Safety glasses with side shields	Nitrile gloves	None required

TABLE 8 1 (Continued) Personal Protective Equipment Summary

Task	Level	Body	Foot	Head ¹	Eye	Hand	Respirator ²
Calibration of flow meters and pumps	D	Work Clothes	Safety shoes	None Required	Safety glasses	None require d	None required
Collecting water samples	D	Work Clothes	Safety shoes	None Required	Safety glasses with full face splash shield	Nitrile gloves	None required
Repair or disassembly of process piping or opening of oxidation chamber	D or C	Work Clothes	Safety shoes with latex boot covers	Hardhat	Splash proof goggle	Nitrile outer gloves with latex inner liners	May require APR with MSA GMC H cartridges or equivalent if VOCs >1 ppm in breathing zone
Clean up of small spills	See Table 7 1	See Table 7 1	See Table 7 1	See Table 7 1	See Table 7 1	See Table 7 1	See Table 7 1
Miscellaneous maintenance work	D	Work Clothes	Safety shoes	Hardhat	Safety glasses	None require d or leather work gloves as needed	None required
Filling acid/caustic tanks	D or C	Work Clothes with protective apron	Safety shoes	None required	Splash proof goggle s or full face splash shield	Elbow length nitrile gloves	None required unless there is a spill
Handling liquid nitrogen	D	Work Clothes	Safety shoes	None required	Splash proof goggle	Leather work gloves	None required

¹ The Subcontractor Health and Safety Officer and EG&G shall specify hardhat areas

² Respiratory protection requirements based upon continuing monitoring for airborne contaminations as discussed in Section 8.0

8 1 CLOTHING

The use of Level D protective equipment is defined by the following criteria

- No contaminants are present or contaminants are present below the action levels established in the HASP for respirator use and
- Work functions preclude splashes immersion or potential for unexpected inhalation of any chemicals

Experience with previous treatment operations indicates that the chance of encountering contamination in the work area is minimal given the low concentration of contaminants. Therefore, Level D protection will be adequate during most normal work activities. This is a field work uniform affording minimal protection, consisting of the following PPE.

- Safety boots leather or chemical resistant with steel toe and shank (not required for non working supervisory personnel or casual visitors under escort)
- Safety glasses (ANSI Z87 1 1989 compliant) with side shields or goggles

The following additional PPE may be required as part of Level D protection depending on the specific tasks being performed

- Coveralls
- Work gloves
- Hard hat with face shield

In addition proper chemical resistant gloves shall be worn when handling process treatment chemicals. Face shields and aprons shall also be worn during operations with the potential for splashing. A poly coated Tyvek suit may also be worn if the splashing potential is judged to be high

Tank top shirts shorts and tennis shoes are not permissible. PPE shall meet the requirements applicable to ANSI and OSHA standards. Where appropriate and more stringent the subcontractor will comply with EG&G Rocky Flats Plant PPE requirements. Modifications or substitutions of the PPE specified herein shall be subject to written approval by EG&G.

If air monitoring as described in Section 9 0 indicates the presence of organic vapors in excess of action levels. Level C PPE may be required. The PPE for Level C shall include the following.

- Full face air purifying respirator with appropriate cartridges or canisters
- Chemical resistant clothing consisting of

coveralls
hooded one or two piece chemical splash suit or
chemical resistant hood and apron or
disposable chemical resistant coveralls
inner and outer chemical resistant gloves and
chemical resistant safety boots with steel toes

Optional

hard hat
outer disposable chemical resistant boot covers
face shield
2 way intrinsically safe radios
long cotton underwear

The criteria to evaluate when considering whether Level C PPE is required include the following

- Oxygen concentrations are greater than 19 5 percent and less than 23 5 percent by volume
- Measured air concentrations of identified substances will be reduced by the respirator below the PEL_TLV or REL and the concentration is within the service limit of the cartridge
- Atmospheric contaminant concentrations do not exceed IDLH levels
- Atmospheric contaminants liquid splashes or other direct contact will not adversely affect anyone left unprotected by chemical resistant clothing
- Job functions do not require self contained breathing apparatus and
- Continuous direct readings on monitoring instruments—such as FiDs or PIDs—are within the action levels prescribed in the HASP for air purifying respirator use

The main selection criterion for Level C as opposed to the more restrictive Level B is that conditions permit wearing air purifying respirators. Cartridges must be able to remove the substances encountered

A full face air purifying respirator can be used only if

- The substance has adequate warning properties
- The individual using the mask has passed at least a qualitative fit test
- The individual has medical clearance for the use of respirators and
- The appropriate cartridge is used and its service limit concentration is not exceeded

The chemical and radiological hazards expected to be encountered at the OU1 Groundwater Treatment Facility were discussed previously in Section 5 0 and presented on Tables 5 2 5 3 5 4 and 5 5. It is apparent from reviewing this information that a supplied air respirators are necessary. These are not maintained at the facility. In the event that their use is required the subcontractor personnel would evacuate and personnel trained in the use of Level B would be required to respond. If experience and data indicate that the contaminants are significantly different than those discussed in Section 5 0, then the respiratory protection requirements must be reevaluated.

An air surveillance program is part of all hazardous material/waste site operations when atmospheric contamination is known or suspected. It is mandatory that the ambient air be thoroughly and continuously monitored when personnel are wearing air purifying respirators. Surveillance using a photoionization detector (PID) colorimetric tubes or other air sampling equipment, in accordance with the HASP is required during all Level C and B operations to detect changes in air quality necessitating a higher level of respiratory protection. Level C protection with an air purifying respirator will be worn routinely in an atmosphere only after the type of air contaminant is identified concentrations measured, and the criteria for wearing air purifying respirators are met

82 RESPIRATORY PROTECTION

The requirements for respiratory protection have been discussed briefly in Section 8 1 and will be presented in greater detail in this section. Respiratory protection requirements shall be based on air monitoring data. Air quality shall be monitored with a photoionization detector (PID) equipped with an 11 7 eV lamp colorimetric tubes or personal air samplers. Action levels for respiratory protection shall be as follows.

As can be seen from the data in Table 5.1 there is the potential for several Volatile
 Organic Compounds (VOCs) to be present in the wastewater to be treated. These
 VOCs and their respective permissible exposure limits (PEL) are

Compound	PEL
Methylene Chloride	500 ppm
Acetone	750 ppm
Carbon Disulfide	4 ppm
1 1 Dichloroethylene	1 ppm
1 1 Dichloroethane	100 ppm
1 2 Dichloroethene	200 ppm
1 1 1 Trichloroethane	350 ppm
Carbon Tetrachloride	2 ppm
Trichloroethylene	50 ppm
1 1 2 Trichloroethane	10 ppm
Tetrachloroethylene	25 ppm
Toluene	100 ppm

 Table 5 2 presents analytical data from influent sampling performed from April 1992 to September 1992. This data shows the following significant contaminants normally present in the wastewater and the associated PEL.

COMPOUND	PEL
Tetrachloroethene	25 ppm
Trichloroethene	50 ppm

Exposure to the VOCs listed would occur only when breaking the integrity of the UV/H_2O_2 system influent piping (e.g. system maintenance or sampling). When necessary to perform maintenance on the influent system or perform system sampling recent waste water influent samples shall be reviewed for actual contaminants and concentrations present. Air monitoring of void spaces (e.g. UV/H_2O_2 unit) after draining and the immediate work area when performing influent sampling will be accomplished with a PID. Should the PID indicate levels above 50% of the most limiting PEL (25 ppm for Tetrachloroethene). monitoring with colorimetric tubes or personal air samplers may also be determined to be necessary to supplement data concerning specific compounds. Analysis of cartridges from personal air samplers would be performed for the compounds of interest by an independent industrial laboratory approved by EG&G. Following completion of characterization of the compounds present, the appropriate air monitoring

administrative controls and personal protective equipment regimes would be determined with the approval of EG&G

The atmosphere in the treatment facility will be monitored weekly when the system is operational with a calibrated PID and if detectable levels are measured at 50% of the most limiting PEL the work area shall be evacuated immediately. The area will then be evaluated to determine the compound(s) present by personnel wearing the appropriate respiratory protection. The subcontractor Health and Safety Officer. Project Manager and the Project Health and Safety Officer will review the results of this evaluation to determine whether engineering controls can be installed to minimize the concentration of VOCs. If engineering controls can be utilized, they will be recommended, and installed upon approval.

If engineering controls are not practical work may continue only after air monitoring results are completed and with the concurrence of the subcontractor Health and Safety Officer and EG&G

8 3 GENERAL REQUIREMENTS FOR PROCESS CHEMICAL HANDLING

Hydrogen peroxide is routinely used during waste treatment in the UV/H₂O₂ system During regeneration of the ion exchange resins—the treatment facility uses hydrochloric acid and sodium hydroxide in bulk quantities—Direct contact with all chemicals shall be prevented with the use of chemical resistant personal protective equipment as described in Table 8.1—and Section 8.1—Clothing to include chemical resistant boots—gloves apron and face shield—The subcontractor operations personnel shall ensure that the emergency shower and eyewash are in operable condition prior to handling process chemical materials—Emergency eyewash and shower facilities shall be inspected and the condition documented at least once per week—Handling and transfer of chemicals shall not be performed by personnel wearing contact lenses—Transfer of chemicals shall be performed only within approved secondary containment areas of the groundwater

treatment facility Chemicals should never be mixed outside the parameters given in the Operations and Maintenance Manual

8 4 GENERAL REQUIREMENTS FOR CHEMICAL STORAGE

Chemicals shall be stored in the approved chemical storage tanks to prevent inadvertent mixing of incompatible materials. Container labeling shall be maintained in accordance with EG&G Rocky Flats requirements and the NFPA hazard warning system.

8 5 CONFINED SPACE ENTRY

Posting of and entry into Confined Spaces will be performed according to EG&G Confined Space Entry procedures by personnel who have received the appropriate EG&G training

8 6 COMPRESSED GAS HANDLING AND STORAGE

The treatment facility includes a gas chromatograph which uses compressed gases Specifically these gases include nitrogen helium hydrogen and air. Cylinders will be stored handled transported and used in accordance with the requirements contained in 29 CFR 1910 101. Compressed Gases. 29 CFR 1910 103. Hydrogen and HSP 11 01. Compressed Gas Cylinders.

9 0 AREA MONITORING

Monitoring of the environmental conditions in and around OU1 must occur because of the potential for contaminants to be present in environmental media, the water being treated filters and ion exchange resins. The following sections describe the monitoring program to be implemented and appropriate exposure limits and actions levels. Where feasible personnel exposures to hazardous materials (other than radioactive substances) shall be maintained within the TLVs adopted by the ACGIH or the PELs adopted by OSHA, whichever is more stringent. Exposure to radioactive material will be maintained below the EG&G administrative limits. Table 9.1 presents a summary of the monitoring program.

9 1 CHEMICAL MONITORING

Air monitoring shall be conducted in and around the OU1 facility using a PID device with at least an 11 5 eV lamp at a minimum of once weekly and during the following tasks when sampling water when changing bag filters and when changing or cleaning UV bulbs. These devices are used to monitor for the presence of volatile organic compounds. PID devices are used as a screening instrument to detect the presence of organic compounds but cannot quantify or identify specific organic substances. The PID will be calibrated with a 100 ppm standard of isobutylene prior to use. If any reading above 50% of the most limiting PEL is found the Health and Safety Officer will investigate to determine the source and will make the necessary changes to reduce the concentration below 50% of the PEL. Monitoring with colorimetric tubes and/or personal air samplers to determine the compound(s) present may be necessary. Monitoring will be performed should the subcontractor find it necessary to break the integrity of the influent system as discussed in Section 8.2

TABLE 9 1

Monitoring Program Summary

Hazard/Sample Type	Action Level	Precaution if Action Level is Exceeded	Monitoring Frequency	
RADIATION				
Equipment and material contamination	Alpha contamination > 20 dpm/100cm² removable > 300 dpm/100cm² total Beta/gamma contamination > 1000 dpm/100cm² removable > 5000 dpm/100cm² total	Equipment and material decontamination	Prior to removal from radiological control area	
Personnel contamination	Background	Personnel decontamination	Prior to exiting access control	
Long lived radioactive airborne particulates	10% of the DAC (if respirators not worn)	Full face piece air purifying respirators (APRs) with HEPA cartridges	As determined by EG&G	
External shallow beta/gamma radiation exposure rate	>5 mrem per hour	Remove personnel from elevated beta/gamma exposure rate area and investigate source	As specified in Section 9 2 3	
CHEMICAL				
Air monitoring for volatile organic compounds	50% of the most limiting PEL for compounds present	Full face air purifying respirators with organic vapor acid fumes cartridges	As specified in Section 9 1	
MISCELLANEOUS MONITORING				
NOISE				

Area	85 decibels 8 hour Time Weighted Average (TWA)	Suitable hearing protection	At discretion of the subcontractor Health and Safety Officer and EG&G IH
------	--	-----------------------------	--

TABLE 9 1 (Continued)

Monitoring Program Summary

HEAT STRESS			
Oral and heart rate monitoring ^b	Oral temperature 38 C (99 6 F) heart rate 110 bpm	Use of ice vests reduce work cycle duration or other EG&G approved measures	Monitoring frequency will be dependent on work area temperature and at the discretion of the subcontractor Health and Safety Officer and EG&G IH

DAC Derived Air Concentration

Work can be resumed provided that the monitoring results can be reduced to less than 50% of the PEL if readings are more than 50% of the PEL it will be necessary to don respiratory protection and to investigate to determine the compound(s) present the source of the compound and whether the use of engineering controls can reduce concentrations to less than 50% of the PEL

Air monitoring may also be done utilizing colorimetric tubes for any of the VOCs present Any indication of concentrations exceeding the PEL for a specific compound will require work to stop unless Level C respiratory protection (full face APR) is donned

Compliance with limits on airborne metal contaminants can be reasonably assured if dust concentrations in the worker breathing zone are kept under control

9 2 RADIOLOGICAL MONITORING

The radiation exposure of an occupational worker will be maintained as far below the U.S. Department of Energy (DOE) limits as is reasonably achievable. An EG&G annual administrative dose equivalent level of 1 800 mrem committed effective dose equivalent.

^b Monitoring will be performed when work area temperature exceeds 85 Fand coveralls or protective clothing is being worn

will be in effect. If any worker exceeds the administrative dose equivalent level a comprehensive evaluation will be performed and if necessary, the employee will be reassigned to a job where his or her radiation exposure will not exceed an additional 100 mrem for the remainder of the calendar year.

9 2 1 Personnel and Equipment Contamination

Personnel and equipment leaving the radiologically controlled area will be monitored for radiological contamination in accordance with the action levels specified in Table 9.1 Release of all equipment and materials from a radiologically controlled area will be in accordance with EG&G Procedures HSP 18.10 and EMRG 3.02. Instrumentation used for personnel and equipment contamination monitoring will be those recommended by EG&G Radiological Engineering. Any alternates will be approved by the HSS and EG&G Radiological Engineering.

9 2 2 Radioactive Air Particulate Monitoring

EG&G is responsible for air sampling for radioactive airborne particulates. These samples will be taken in the breathing zone of workers, within the work zone, and outside the work zone.

Workers may be required to wear personal air monitoring devices to sample for radioactive particulates in the worker's breathing zone. Air sampling in the work areas will be performed at the discretion of EG&G. Area sampling may also be performed in locations within and outside the work zone.

9 2 3 External Beta/Gamma Radiation Monitoring

After successful completion of the medical and training requirements specified in Section 6.0 of this plan all employees who will work within the controlled area will be issued

radiation monitoring badges by EG&G Dosimetry These badges are required only when performing tasks such as ion exchanger resin replacement and are not necessary for access to Building 891

9 2 4 Internal Radiation Exposure (Bioassay) Monitoring

The subcontractor employees who are issued radiation monitoring badges are subject to periodic urine and/or fecal samples at the discretion of EG&G. Additional urine and/or fecal bioassay samples may be required at the discretion of EG&G if a substantial exposure is suspected. These samples will be analyzed for radionuclides to determine whether the employee has received an internal radiation dose while performing work at OU1. Sample containers will be provided by EG&G.

9 3 MISCELLANEOUS MONITORING

9 3 1 Noise Monitoring

Sound pressure levels shall be monitored to delineate hearing protection areas Monitoring frequency will be at the discretion of the subcontractor Health and Safety Officer. Additionally, a personal noise dosimeter may be used in conjunction with a sound level meter in order to assess noise exposures of selected individuals based upon area monitoring. Suitable hearing protection shall be worn in areas with noise levels greater than 85 decibels. The subcontractor personnel shall be required to follow the requirements of an effective hearing conservation plan including audiometric testing if working in an area requiring hearing protection.

9 3 2 Heat Stress Monitoring

Monitoring will generally consist of periodic measurement of workers body temperature and heart rate during periods when work area temperatures exceed 85°F and protective coveralls are required to be worn. Monitoring frequency will be determined by the subcontractor Health and Safety Officer and EG&G Industrial Hygiene and will depend on the work area temperature and the type of work being performed

10 0 SITE CONTROL

Within the controlled access area there are restricted and unrestricted areas. In general controlled access areas in which radioactive or chemical contamination is present above established guidelines are restricted areas. Restricted area signs have been posted indicating the nature of contamination present in each of these areas. Controlled access areas in which site characterization data has indicated that no significant chemical and radiological hazard is present are unrestricted areas. Subcontractor personnel shall not be permitted access to restricted areas of the site other than those included in the scope of this project unless specifically authorized access by EG&G. Access to all areas posted as confined spaces shall be in accordance with established EG&G Procedures.

Access to the OU1 groundwater treatment facility shall be controlled by the subcontractor operations personnel when present. A log in sheet located in the facility office will be implemented to record the presence of all personnel including visitors. The subcontractor Operators will be responsible for escorting visitors and providing a short documented briefing concerning hazards associated with visiting the groundwater treatment facility.

APPENDIX A Material Safety Data Sheets

Material Safety Data Sheet

from Genium's Reference Collection
Genium Publishing Corporation
1145 Catalyn Street
Schenectady NY 12303 1836 USA
(518) 377-8855



No 30A

HYDROCHLORIC ACID

(Revision B)

Issued October 1977 Revised November 1988

SECTION 1 MATERIAL IDENTIFICATION		27
Material Name HYDROCHLORIC ACID		
Description (Origin/Uses) Used in the production of chlorides in refining for the neutralization of bases for pickling and cleaning metal products for our scale from boilers and heat-exchange equipment.	ore in the pro	I treatments, and in temoving
Other Designations: Aqueous Hydrogen Chloride Munauc Ac.d 'HC' H,O	CAS No 7647	HMIS 7-01-0 H 3 R 1 F 0 f 4
Manufacturer- Contact your supplier or distributor Consult the latest edition Buyers Guide (Genium ref 73) for a list of suppliers.		F 0 I 4 R 0 S 4 PPG S 4 See sect 8 K 0
SECTION 2 INGREDIENTS AND HAZARDS	%	EXPOSURE LIMITS
Hydrogen Chlonde, CAS No 7647-01-0	38 or Less	OSHA PEL
Water	Balance	Ceiling. 5 ppm, 7 mg/m ³ ACGIHTLV 1983-89 TLV-Ceiling 5 ppm, 7 mg/m ³
Impurities such as iron chlorine, and traces of organic matter may be present in small amounts depending on the grade of acid Ser NIOSH RTECS (MW4025000) for additional data with references to reproductive and mutagenic effects. Continue to monitor NIOSH, RTECS (MW40300000) for toxicity data on hydrochloric acid itself		Toxicity Data ² Human, Inhaiatoon, LC., 1300 ppm (30 Mins) Rat, Inhaiatoon LC ₂₂ , 3124 ppm (1 Hr) Rabbut, Oral, LD ₂₂ , 900 mg/kg
ECTION 3 PHYSICAL DATA		

ECTION 3 PHYSICAL DATA

Soiling Point 227°F (109°C) (20.22%)

Melting Point 35°F (65°C) (20.69%)

Vapor Density (Air = 1) 1.68

pH Strong Mineral Acid

Molecular Weight. Not Applicable
Solubility in Water (%) Complete
Specific Gravity (H₁O = 1) >1
% Volatile by Volume: Ca 100

Appearance and Odor. A clear colorless-to-lightly yellowed, fuming liquid sharp pungent, characteristic, unitating odor of hydrogen chloride gas. This odor is detectable at 1 to 5 ppm and becomes unpleasant and unitating at 5 to 10 ppm, however the odor serves as a good warning property

Comments. The specific physical properties of aqueous hydrochloric acid solutions vary with the amount of dissolved hydrogen chloride gas. Hydrochloric acid forms a constant boiling azeogrope (a mixture of hydrochloric acid and water that behaves like a single substance in that its varor has the same composition as the mixture itself) with water (at 227°F or 109°C) that contains 20.22% hydrogen chloride and has a decisty of 1 096. Boiling weaker or stronger aqueous solutions results in the loss of either component until the constant boiling ac d is

SECTION 4_ FIRE	AND EXPLOSION DATA	LEL	UEL
Flash Point and Method	Autoignition Temperature		

Extinguishing Media Hydrochloric acid solutions do not burn. Use extinguishing agents that will put out the surrounding fire. Unusual Fire or Explosion Hazards. Use a water spray to cool fire-exposed containers of hydrochloric acid to prevent ruptures. Explosive hydrogen gas can be produced by the reaction of hydrochloric acid with metals such as iron. Neutralize spilled hydrochloric acid with limestone, slaked lime or soda ish to minimize the possible generation of hydrogen gas. Special Fire fighting Procedures. Wear a self-contained breathing apparatus (SC3A) with a full facepiece operated in the pressure-demand or positive pressure mode. Special neutralization procedures, if applicable include the application of chemically basic substances such as soda ash or slaked lime.

SECTION 5 REACTIVITY DATA

Stability/Polymerization Hydrochione acid is stable in closed containers during routine operations at room amberature. Hazardous polymerization cannot occur. Chemical Incompatibilities. Hydrochione acid reacts dangerously with acetic mhydride, 2 aminochianol ammonium hydroxide. alic um phosphide, chlorosulfonic acid, thylene diamine, thylenimme, oleum, perchloric acid, 3-proposlactone propylene oxide, silver perchlorate and carbon terrachloride, sodium hydroxide, sulfune acid uranium phosphide, vmyl acitate sodium, and many produce compounds (Genium ref. 84). This material is a strong mineral acid that is ery reactive with bases Conditions to Avoid Avoid osure in incompatible chemicals and to any other material whose compatibility with hydrochloric acid or its vapor has not ye been established. The errosive acide of hydrochloric acid on most meals can liberate attentily flammable/explosive hydrogen gas (H.) hiping systems and containment systems must be chosen carefully. Hazardous Products of Decomposition. During fires hydrochloric acid many decompose by recling with certain metals in product, very flammable and axplosive hydrogen gas (H.). Significant amounts of hydrogen chloride gas (HC.) are given off at room temperature the rate of this gine, atton increases as the amperature and he surnight (1%) by we gift of HC in H₂O increase. Comments. Reactions between hydrochloric acid and evanues sulfides, and formaldehyde will produce a transitional hydrogen evan de (HC.N.) hydrogen sulfide (H.2) sulfur dioxide (SO.) and bachloromethylether respectively.

SECTION HEALTH HAZARD INFORMATION

Curcinogenicity Hydrocalonic acid is not listed as a carchogen by the NTP IARC, or USHA.

Summary of Risks: See Genum Industrial MSDS 30 for details of the health effects of hydrogen chloride gas. Hydrochloric acid solutions will generate hydrogen chloride gas with all its health effects. These are irritating to the skin, eyes, and mucous membranes of the upper est puratory tract (URT). The seventy of eye injury from splashes depends upon quantity concentration/strength, and duration of the contract. Permanent visual damage has been reported ingestion of hydrochloric acid causes corresion of the mucous membranes, esophagus and stomach, as well as nausea, vomiting, intense thirst, and diarrhea. Erosion of exposed teeth may occur Circulatory collapse and death are possible Medical Conditions Aggravated by Long Term Exposure None reported. Target Organs Skin, eyes, URT Primary Entry Inhalation, skin contact. Acute Effects. Corrosive skin and eve burns, tissue damage and severe immuon of the URT Chronic Effects None reported FIRST AID Eves, immediately flush eves, inc uding under the eyelids, gently but thoroughly with plenty of running water for at least 15 minutes. Skin Rinse the affected area with flooding amounts of water and then wash it with soap and water Remove contaminated clothing under a safety shower Inhalation. Remove the exposed person to fresh air restore and/or support his or ber breathing is needed. Have qualified medical personne administer oxygen is required. Ingestion, Not kely Should this type of exposure oc ur and the exposed person is responsive give him or her 2 to 3 glasses of water their milk of magnesia or limewater to drink. Do not induce vomiting. Spontaneous laryagest spasms can occur. Never give anything by mouth to someone who is unconscious or convulsing Get medical help (in plant, paramedic community) for all exposures. Seek promot medical assistance for further treatment, observa uon and support after first aid Note to physician. Treatment for respiratory effects following inhalation of hydrogen chloride gas includes using a 5% sodium bicarbonate solution as an aerosol, maintaining a proper fluid balance (diuretics may be useful) and decreasing the in flammatory response of the lungs by ministering steroids on a short term basis (2 to 4 days). Severe inhalation exposure requires hospitalization and observation (72 four minimum) for the delayed onset of pulmonary edema. Serial chest X rays and respiratory support, including intubation, may be required as an early intervention.

LEAK SPILL SECTION AND DISPOSAL PROCEDURES

Spill/Leak Noufy safety personnel, evacuate unnecessary personnel, eliminate all sources of ignition immediately (hydrogen gas may be generated) and provide adequate ventilation. Cleanup personnel need a full set of protective clothing including a self-contained breathing apparatus (SCBA) Small spills and residue can be covered with an excess of a mixture of soda ash and slaked lime. After neutralization do not flush waste directly to a sewer or into lakes, ponds, or streams. Waste Disposal. Contact your supplier or a licensed contractor or detailed recommendations. The allowable concentration of neutral sait in the effluent discharge is apt to be regulated study and follow Federal state, and local regulations. Consider saving the waste hydrochloric acid for use as a neutralizing agent during cleanup operations.

OSHA Designations

Listed as an Air Contaminant (29 CFR 1910 1000 Subpart Z)

EPA Designations (40 CFR 302.4)

CERC...A Hazardous Substance, Reportable Quantity 5000 lbs (2270 kg) per the Clean Water Act (CWA) §311 (b) (4)

SECTION 8 SPECIAL PROTECTION INFORMATION

Goggies Always wear protective eyegiasses or chemical safety goggies. Where splashing is possible, wear a full face shield. Follow OSHA eye and face protection regulations (29 CFR 1910.133). Respirator: Wear a NIOSH approved respirator per Genum reference \$8 for the maximum use concentrations and/or the exposure limits cited in section 2. Follow OSHA respirator regulations (29 CFR 1910 134). For emergency or nonroutine operations (spills or cleaning reactor vessels and storage tanks) wear an SCBA. All respirators must be acid resistant. Warning. Air purifying resourators will not protect workers in oxygen-deficient atmospheres. Other: Wear impervious gloves, boots aprons, gauntiers etc. to prevent any contact with this material. All clothing must be acid resistant. Ventilation install and operate general and local maximum-explosion-proof ventilation systems powerful enough to maintain airporne levels of hydrogen chloride below the OSHA PEL cited in section 2. Local exhaust ventilation is preferred because it prevents dispersion of the contaminant into the general work area by eliminating it at its source. Consult the latest edition of Genium re erence 103 for detailed recommendations. Make ventilation system ductwork and exposed fan components acid renstant. Safety Stations: Make emergency eyewash stations, safety/quick-drench showers and washing facilities available in work areas. Contaminated Equipment Contact lenses pose a special hazard soft lenses may absorb urntants, and all lenses concentrate them. Do not wear contact lenses in any work area. Remove contaminated cothing and launde before wearing it again clean this material from your shoes and equipment. Other Design all engineering systems to be acid resistant and explosion proof (hydrogen gas may be accidentally generated). Comments. Practice good personal hygiener always wash thoroughly after using this material and before eating drinking smoking, using the toiler, or applying cosmetics. Keep it off your cothing and equipment. Avoid transferring it from your hands to your mouth while eating drinking, or smoking. Do not eat, drink, or smoke in any work area. Do and analy hydrochloric acid vapor

SPECIAL PRECAUTIONS AND COMMENTS SECTION 9

Storage: Segregation Store hydrochloric acid in closed containers in a cool, dry well ventilated area away from sources of ignition, strong oxidizers strong bases out of direct studight, and away from incompatible chemicals (see sect. 5) Protect containers from physical damage Special Handling/Storage Storage areas should have acid resistant floors and approved drainage facilities. Use nonsparking tools in areas around tanks and pipes where hydrogen gas may be generated. Engineering Controls. Make sure all engineering systems (production, transportation) are of maximum-explosion-proof design. Ground and bond all containers and pipelines, etc. used in snipping transferring reacting production and sampling operations to event static sparks. Hydrogen gas may become concentrated inside me all equipment perform operations to search out possible hidden areas of hydrogen gas carefully. Other Precautions. Carefully follow our supplier's recommendations concerning the proper handling and storage procedures or hydrochloric acid. Provide emergency neutralization materials (soda ish limistone, or staked lime) and equipment near storage and use areas.

Transportation Data J CFR 172 101 2)

DOT Shipping Name Hydrochionic Acid DOT Hazard Class. Corrosive Material

ID to UN1789 DOT Label Comosive

DOT Packaging Requirements, DOT Packaging Exceptions 49 CFR 173.263

IMO Shipping Yamer Hydrochlone Acid, Solution

IMO Hazard Class \$

IMO Label Corross e

IMDG Packaging Group II

References 1 76 38 34-94 100 116 117 120 122

In the to be the control of formation been f purchased purposes are ecentarily pure as a responsi hity merelo et although ressonable care has been tak in he preparate of uch formation Genium Publishing Cara. שצורצה כב, רוצובו בס הבסרבובתנאנ מג ומה ונגוותים בה הבסספוםעוון re to the accurac succept by fact aformation f application to L- Mer tesded purposes pasequences of 2 use.

Propared by PJ Igoe BS

Industrial Hyg ene Review DJ Wilson CIH

Medical Review W Silverman. VID

C		·								
Sec ion i				me			**************************************			
Product	Hydrogen Peroxide 507			Emergency Assistance Chemirec 1 800-424 9300					7	
Chemical/ Synonyms	H ₂ 0 ₂ /Perox1de			P.S.I (602)-327-3277			,	Health	2	1
Chemical Camily	Inorganic Per	oxide)	est	ard Ratin	g Silght	Fre	0	
C.A.S. Number	7722 84-1	UN Number	2014			Extreme 4	Reactivity	2	_	
Section II			Ingre							
	Composition) 3	4	<u> </u>		TOXIO	city Oata		
Water	Hydrogen Peroxide Water Stabilizers 50 50 0ral LD50 2gm/kg (mouse) Trace									
Section III			Shuese	o Dete	,					
Sa ling Paint				18 @ 85°C						
Spec fic Gravity	1 195 @ 68°F	% Volstile Volume	% Volatile By 100 Vapor Density							
Complete Evaporation Rate Water Complete (Butyl Acetate 1) Less than 1										
Appearance And	Odor Clear co	olorless liq	juid C	once	ntrat	ons o	ver 35%	may have sharp o	dor	-
Sec ion IV			Reac	livity						
Stability	Unstable	X Stable	Hazardo	us Pol	ymenzst	ion	□ ма	y Occur X Will Not	Occui	r
Contamination reducing as decomposition and may be steam Conconstruction that the construction of the cons	on The rate very vigorous	ox.dizers of decompos s with rapid it.on Syste	alkalie iton 1 i genera ems In	s ar ncre	nd par ases n of 1	t_cula with . large	ate soli rcreasi volumes	ds will cause of ovvgen and		

Section V	Fire And Explosion Hazzets				
Flash Point And Method Used	Flammable Limits (% Volume in Air)	Lower Ugger			
NA	non-flammable				

Extinguishing Media

Water

Special Fire Fighting Procedures And Precautions

Hear protective clothing and self contained breathing apparatus

Unusual Fire And Explosion Hazards

Surong oxidizer Hydrogen peroxide is not flammable but can initiate spontaneous compustion or paper wood cloth, and other organic materials. Ignition may be rapid but can be delayed for several hours. Rapid oxygen evolution from decomposing hydrogen peroxide may increase the intensity of a fire

Oxygen enrichment of poorly ventilated organic atmospheres increases the potent al or vapor phase explosions

Sec ion VI

Emergency And First Aid Procedures

Skin/eyes Fiush with large amounts of water for at least 15 minutes. Quickly remove contaminated clothing and shoes. Flush clothing with large amounts or water Contact a physician in case of eye contact with peroxide.

Indestion Orink large amounts of water to dilute Sit upright Contact physician

Note to Physician

It may be advisable to insert a gastric tube or relieve or prevent increased pressure that may result from the rapid evolution of oxygen upon decomposition

Innalation Remove victim to fresh air Contact a physician

Section VII

Employee Protection

Respiratory Protection

Self contained breathing apparatus should be available

Protective Cathing

Adequate eye protection rubber gloves and boots, PVC slicker suit

Additional Protective Measures

Water source and safety shower/eye wash should be located close to where hydrogen peroxide is handled

Section VIII

Health Information

Exposure to skin or eyes may cause chemical burns. Inhalation of vapor or mish may cause irritation or chemical burns to mucous membranes and respiratory system.

Ingestion may cause chemical burns as well as injury by distention of the esophagu or stomach due to the sudden evolution of gasses

Section IX

Occupational Exposure Limits

ACGIH - TLV - TWA 1 ppm

OSHA 8 hour time weight average (TWA) = I ppm

and the second

Section X

Environmental Protection

Soill Or Leak Procedures

Flush spill area with large amounts or water Do not return spilled material to original container. Comply with Federal State and local regulations or reporting spills.

Waste Oisposal

Dilute with large amounts of water then flush to sewer Comp y will Federal State and local regulations

Environmental Hazards

Yone

perox-gard. Hydrogen Peroxide

Section Al		Special Precautions			
2) Do not conta -) Storage co vented and steel or Systems I	ig hydrogen peroxic iminate hydrogen per entainers/vessel i made of compat high purity alu inc for addition i materials	eroxide s for hydroge ble plastics minum Conta	n peroxide mu , 304 or 316 ct Peroxidati	st be stainless on	
Sec ion XII	Tea	nsportation Requiremen	18		
Department Of Transporation Classification	Flammable Liquid Flammable Solid Flammable Gas	Combustible Liquid Poison Class A Poison C ass S	Oxidizing Material Corrosive Material Irritating Material	Non Flammable Gas Not Hazardous Sy 0 0 ~ Regulations Other Specify Below	
OOT Proper Shipping Name Hydrogen peroxide Other Regulations Hydrogen peroxide material when ship	solution 50% per	below 52° is no	t regulated as	a hazardous	
Section XIII	0	ther Regulatory Controls)		
Contains stabilizers and promoters compatible for use with the perox-cure UV/Tycrogen Peroxice chemical oxidation process and perox-gard sulfide control services TCA - Tood grade hydrogen peroxide must meet Food Chemical Code specifications					
o he bes of our knowledge and Salety Data Shi	eet s accurate. Howeve	er Peroxidation			
Sys ems makes no warranty expressed or implied or accepts any lability in connection with his information or its use Date Prepared MAY 1989					

MATERIAL SAFETY DATA SHEET GENIUM PUBLISHING CORPORATION



34 MSDS # _ SOOTUM YYDROXIDE 50% LIQUID

Revision A issued October 1977 Revued Augus 1935

1 53

12 76

45 CATALYN ST SCHENECTADY NY 12303 USA (518) 377-8854

om Genium i MSDS Collection to be used as a reference

SECTION 1 MATERIAL IDENTIFICATION

1-

MATERIAL NAME SOOILM HYDROXIDE 50% LIQUID

OTHER DESIGNATIONS Liquid caustic sods lye solution CAS #1310-73-2 (NaOH)

MANUFACTURER Available from many sources including

Diamond Shamrock Co Chlor Alkali Div

331 Pheirs Court Box 152300

Ir/ing TX 75015 2300

4داد 241 (800)



SECTION 2 INGREDIENTS AND HAZARDS		∞	HAZARD DATA
SODIUM HYDROXIDE (VaOH)		>48 5	Ceiling Limi 2 mg/m.
TYPICAL IMPURITIES Carbonate (as Na ₂ CO ₃)		<0 25	1% NaOH Soin
Chloride (as MaC) Chlorate (as MaCl0)	مراجع	<1 15 <0 25	Eye rabbit Severe
Sulfate (as Wa ₂ SO ₄)	, ' (<0 03	'ITICAC'ON
Silica (as SiO _Z)	į.	<0 01	
Mater Curr nt (1985-86) ACGIH TLV Current OSHA PFL is 2-0 m;		balance 8 hours	

Specific gravity 60/60°F

Density, 15s/gal

SECTION 3 PHYSICAL DATA

ing point latm atiles (water)

ca 140°C

50%

er Solubility

complete

Viscosit/ 9 20°C cps

50

APPEARANCE & ODOR Clear liquid - No odor

DESCRIPTION A 50% solution of sodium hydroxide (NaOH) in water

SECTION 4 FIRE AND EXP	ECTION 4 FIRE AND EXPLOSION DATA			
Flash Point and Method	Flash Point and Method Autotgassion Temp Plansmebility Limits it Air			
Yone rot combustible	· VÀ!	N/A	Y/A	V/A

EXTIGUISHING MEDIA
Use extinguishing agents suitable for the surrounding fire. Use water suray to cool containers or this mater al which ar involved in a fire situa ion to help prevent rupture Sodium hydrox de will read with metals such as aluminum tin and inc to generate frammable and explosive hydrogen gas

ringhters should wear self contained breathing apparatus and ull protective gear in prevent contac with his cormosive material

SECTION 5 REACTIVITY DATA

This mainstable under normal storage conditions in sealed containers. Polymer at on will not occur. Ther ar no ha ardous decompos on producis. It read a vith CO in he air to orm socium carbonate $^-$ ac s violently 41 h ac ds accompanied by heat generation and 41 h many organic chemicals especially arbons and halocarbons I can read with religiously lene of orm spontaneously ammable toace flene

Toon acoust heather and wool. Contacows has aluminum to magnesium or and alloys has on a h hese he als causes he ormation of hydrogen gas (SOS #65) (*12mmaule)

water and

SECTION 6 HEALTH HAZARD INFORMATION

TLY Ceiling Unit 7 mg/m3

Sodium Hydroxide is a strong alkali and is dangerous when improperly handled. It is destructive to all hums tissue it contacts producing severe burns. Eye contact causes severe permanent injury fair contact causes in attorniand in not removed immediately severe burns with scarring. The effects of inhalation of the mistricant establishment injury fair contact causes severe burns are from mild irritation to destructive burns. Pneumonitis may occur. Ingestion causes severe burns or mouth throat and stomach and may be fatal.

rIRST AID Wash eyes immediately with plenty of running water for at least IS minutes including under ye lids and all sur aces. Speed in rinsing eyes with water is important if permanent injury is to be avoided. Get medical he primmediately SKIN CONTACT. Flush exposed area promotly with large quant lies or water Remove contaminated clothes while washing. Prolong washing in serious cases until medical help articles Get medical attention or serious exposure. INCESTION Immediately give person large quantities or water or milk to drink (Never give anything by mouth to an unconscious person). Do not induce vomiting Obtain medical assistance immediately. INHALATION Remove from exposure of mist and get prompt medical help (Paramed c Inplant community).

SECTION 7 SPILL LEAK AND DISPOSAL PROCEDURES

Planning anead is essent al for handling spills. Clean up personnel should wear protective equipment to one vent skin and eye contact. Pick up spill with vacuum equipment (alkali resistant) for disposal or flush to holding area with water. Yeutrali e residue with dilute acid and rinse with water.

DISPOSAL Waste caustic must never be discharged direc by to sewers drains or surface waters. Dilute well with water and carefully neutralize with ac d. Follow all applicable federal state and local regulations.

EPA 4AZARDOUS WASTE NUMBER DOOZ corrosive (soln c pH >12 5) 40CFR 261 22 REPORTABLE SPILL QUANT TY 1000 1bs (40CFR117)

SECTION 8 SPECIAL PROTECTION INFORMATION

ovide adequate general vent_lat_on and exhaust ventilation to meet TLV requirement especially where their substitution or mist formation exists. Use a NIOSH approved respirator with full face covering for mist where needed. Use chemical safety goggles. A plastic faceshield in addition to safety goggles, should be worm if splashing is probable. Use rubber gloves, apron or protective clothing and rubber boots where needed of prevent contact with sodium hydroxide solution.

Eyewash stations and sarety showers must be immediately available

THIS MATERIAL POSES A SPECIAL HAZARD TO CONTACT LENSES WEARRS the slippery nature of this solution would make it extremely difficult to remove the contact lenses. C-itical mining of the contaminated eye ould be delayed.

SECTION 9 SPECIAL PRECAUTIONS AND COMMENTS

Stor in well sealed containers Protect containers from physical damage. Avoid handling conditions high can lead of spills or mist formation. Have abundant water (preservably running water) available where material is stored unloaded and handled or emergency use. Drains servicing areas where is material is sited or used should have ritention basins for pH adjustment and dilution of spills and flushings be one disclarge. Workers handling his material should be trained in proper handling precautions and emerging procedures with proper protective equipment nearby. Both HAZARD CLASSIFICATION Corrosive Material

DOT LABEL Corrosive DOT ID YUMBER UN1824

DATA SOURCE(S) CODE (See Glosser) 7 4 9 11 12 27 55 58 V

uniquenters as to the notabley of information hereta for partitions: purposes are estimately partitioner responsibility. Therefore charge responses care has been taken in the preparation of such intermetions. Common Profession of programmes and instructions of the information of professions in the information of the

APPROVALS	20) Accross 11/05	
INDUST HYGIENE	SAFE~ 210 11/8-	
MEDICAL REVIEW	= (2) 1° 12	

GENIUM PUBLISHING

Cooludu @ menz

and the same of th

Material Safety Data Sheet

From Genium's Reference Collection Genium Publishing Corporation 1145 Catalyn Street Schenectady NY 12303 1836 USA (518) 377 8855



No 61 NTTROGEN (Revision A)

Issued April 1980 Revised April 1986

SECTION 1 MATERIAL IDENTIFICATION MATERIAL NAME. NITROGEN DESCRIPTION Gas supplied in cylinders (2000+ psig) or cold liquid supplied **HMIS** in vented Dewar containers. 2 OTHER DESIGNATIONS. N2, CAS #7727 37 9 ASTM #D1933 MANUFACTURER/SUPPLIER. Available from several suppliers, including. F 0 Air Products & Chemicals, Inc., Industrial Gas Division, PO Box 538 R 0 Allentown, PA 18105 Telephone: (215) 481-4911 PPE* Aureo Industrial Gases of the Boc Group Inc., 575 Mountain Avenue. *See Sect 8 S 2 (Liquid) Murray Hill, NJ 07974 Telephone (201) 464-81000 Union Carbide Corp., Linde Div., 39 Old Ridgebury Rd., Denbury CT 06817 Telephone; (203) 794-5300 K O

SECTION 2. INGREDIENTS AND HAZARDS % HAZARD DATA

Nitrogen, CAS #7727 37 9 >99.5 No TLV Established.

Oxygen, CAS # 7782-44-7 < 0.5

SECTION 3 PHYSICAL DATA

Boiling Point, 760 mm Hg ... 320 4 F (195.3 C) Vapor Density (Air = 1) ... 0.967 Solubility in Water @ 20 C, Vols/100 vols. ... 1.6 Density (liq) g/cm³ ... 0.8 Meiting Point ... 345 7 F (209.86 C) Critical Temperature ... 232.3 r (1471 C) Critical Pressure, Atm ... 33.5

Molecular Weight ... 28 01

Fanencion Rapo, Liquid to Gas

Expansion Rano, Liquid to Gas @ 70°F 1 696

Appearance and odor: A colorless, odorless tasteless gas or a cryogenic liquid.

SECTION 4 FIRE A	ND EXPLOSION DATA		LOWER	LPPER
Flash Point and Method	Анкондпиров Тетр	Flammability Limits in Air		
Not Found	Not Found	Nonflammable	Not Found	Not Tound

Use extinguishing media that are appropriate to the serrounding fire. Do not discharge solid streams of water into liquid N_2 . Use water spray to cool fire-exposed containers or if desirable, to increase the rate of evaporation of the liquid if the increased rate can be controlled (cryogenic liquid will rapidly freeze water). Nitrogen is a nonflammable material that will not support combustion. It presents no unusual explosion hazard unless the compressed gas is exposed to fire their containers may rupture violently. Nitrogen cylinders are equipped with pressure relief devices that are designed to vent N_2 when they are exposed to elevated temperatures and pressures. When liquid nitrogen is spilled it can release a rapidly vaporizing cloud that will create an oxygen-deficient atmosphere

SECTION 5 REACTIVITY DATA

Nitrogen is stable when stored in closed containers, it does not polymerize. Nitrogen is noncorrosive and is nearly ment at room temperature. At high temperatures it can combine with oxygen to form oxides, and with hydrogen to orm ammonia. When heated with carbon in the presence of alkalies or banum oxide it may form cyanides. It can form nitrides with lithium, silicon calcium, strontium, and banum when it is at a red heat.

It has been reported that natrogen can be oxidized explosively by ozone.

Lithium and titanium at an elevated temperature can burn in a nitrogen atmosphere. Bervlium can be ignited in a mixed nitrogen and-carbon dioxide atmosphere

Vitrogen will react with oxygen in the presence of sparking (from an ele tric are or a gas fired furnace) to produce native oxiding gas

SECTION 6 HEALTH HAZARD INFORMATION

Nitrogen is not listed as a carcinogen by the NTP IARC, or OSHA.

This material is nontoxic and is classified as a simple asphyxiant by virtue of its displacement of oxygen. Symptoms of exposure depend on the degree and the duration of oxygen deficiency. They can include increased frequency and volume of breathing increased pulse rate, muscular incoordination, fatigue, nauses, vomiting, and collapse. Inhalation of pure nitrogen atmosphere produces immediate loss of consciousness death follows unless anyoxygen breathing can be quickly restored. Contact with liquid nitrogen or cold vapors can cause cryogenic burns (severe frostbue/freeze burns).

FIRST AID CONTACT WITH LIQUID NITROGEN. Promptly flush areas affected with lots of tepid water to reduce freezing of ussue. (Do not apply direct heat to affected areas!) Do not rub frozen areas. Loosely apply dry sterile, bulky dressings to protect area from infection and from further mjury. Get medical help

INHALATION Caution! Would be rescuers need to be concerned with their own safety in oxygen-deficient areas. Use self contained breathing equipment. Remove victim to fresh air. Quickly restore and/or support his breathing as required, administering oxygen if available. Get medical help

INGESTION Get medical help <u>ACUTE FFFECTS</u> Gas Simple asphyxiation by displacement of oxygen. Liquid Cryogenic burns. <u>PRIMARY ENTRY</u> inhalation

GET MEDICAL ASSISTANCE = in plant, paramedic, community Get medical help for further treatment, observation and support after first aid.

SECTION 7 SPILL, LEAK AND DISPOSAL PROCEDURES

Nouly safety personnel of major nitrogen leaks or spills. Shut off leak if you can do so without risk. Evacuate all personnel from the danger area until ventilation can restore a safe oxygen level. Emergency personnel need self-contained breathing equipment. Minor leaks (which are dangerous in enclosed areas) can be detected by painting the suspected area of leakage with a soap solution. Prevent liquid nitrogen from contacting vulnerable steel structures and vehicle tires (see sect. 9). Allow spilled liquid to evaporate.

DISPOSAL. Remove a liquid nitrogen container or leaking cylinder outdoors or place into a hood with good forced ventilation. Allow gas to discharge at a moderate rate. Defective cylinders should be tagged to indicate defect. Close the valve and return the defective cylinder to supplier.

SECTION & SPECIAL PROTECTION INFORMATION -

Provide adequate general and local exhaust venulation to prevent workplace atmospheres from becoming oxygen deficient (minimum O₂ volume = 18%). Provide air-supplied or self-contained breathing equipment for emergency or nonroutine situations where the nitrogen level is excessive. Use a safety line and a standby worker when respirator protected personnel enter a hazardously nitrogen-enriched area. (The standby worker should have a self-contained breathing apparatus immediately available.) Those working with liquid nitrogen should wear approved insulating gloves, safety glasses, and other protective clothing as required by use conditions to prevent any skin contact with liquid nitrogen. Cuffless trousers should be worn outside high topped shoes. Safety shoes are recommended for those handling cylinders of gases

Wear safety gloves and approved insulated gloves. Use air supplied or self-contained breathing apparatus

Contact lenses pose a special hazard soft lenses may absorb irritants, and all lenses concentrate them.

SECTION 9 SPECIAL PRECAUTIONS AND COMMENTS

STORAGE SEGREGATION Store in a cool, dry well ventilated low fire-risk area. Protect containers against physical damage.

SPECIAL HANDLING/STORAGE. Protect containers from extremes of temperature and weather (Do not allow any part of a compressed gas cylinder to be exposed to temperatures above 125°F [51 6 C]). Follow general safety procedures for handling and securing compressed gas cylinders. Liquid nitrogen storage areas should be kept clean and free from flammable materials. Make sure that liquid nitrogen containers are properly vented to prevent buildup of pressure. All pressure equipment and process lines should be designed so that the minimum burst pressure is at least four (4) times the expected maximum pressure. Certain materials are unsuitable for service in contact with liquid nitrogen because they become extremely brittle and can be readily shattered by impact.

DOT Classification. Nonflammable Gas

UN1066 (Compressed) UN1977 (Cryogenic Liquid)

LABEL Nonflammable Gas

Data Source(s) Code 1 4-11 14 17 25 51 63 32 34 CK

udgements as to the autability of information herein for purchaser's purposes are accessantly purchaser's responsibility. Therefore, although responsible care has been taken in the preparation of such information. Conjum Publishs is Corp. extends a warranies, makes no responsibilities and assumes no responsibility as to its accuracy or sunability of such information for application to purchaser's metadod purposes. For consequences of its use.

Approvais 900 Ourses 1/87

Indust. Hygiene/Safety

7

Medical Review

Copyright © April 1 1986

Converges © 1986 General Perluding Corporates. As comparess of reproduction wildow for full laber perfession problems.

and district

